

05 Tires and Rims Condition

05.A Front Tyre

TEST CERTIFICATE

الاطار الامامى

Site Number 08 May 2022, 17:24:22 **840-Emirates Auctions** Transaction Date

Transaction Number 54205978 (CC10006) **Oueue Number** 312309



Chassis Number 1GNKVJED8BJ109256

Engine Number

Vehicle Class Car

Manufacturer Chevrolet Model **Traverse**

Model Year 2011

Color Silver

49709 Miles Mileage

Fuel Type Petrol

No. Of Cylinders

Specification **USA** Imported

REMARKS DEFECT

01 Body		جسم المركبة
01.A Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENT,SCRATCHE	الصبغ
01.B Rusty	UNDER BODY PARTS & SUSPENTION, FLOOR, CHASSIS RUSTY	صدأ
01.C Doors	REAR RIGHT SIDE PORTION REPAIRED, REPAINTED & FRONT RIGHT SIDE PORTION REPAINTED	أبواب

02 Engine Condition المحرك

02.A Visual Engine Condition ENGINE NOT START ALL SYSTEM NOT CHECK & OIL LEAK حالة المحرك النظرى

03 Interior Condition الحاله الداخليه

03.A AC Condition **NOT CHECK** المكيف

04 Lights الاضاءة

ALL LIGHT NOT CHECK 04.A Head Light الاضاءة الرئيسية

الاطارات

BOTH SIDE 2019

BOTH SIDE 2018 WORN OUT 05.B Rear Tyre الاطار الخلفى

DEFECT	REMARKS	
06 Exhaust System		نظام العادم
06.A Other	EXHAUST HOSE MISSING	اخري
07 Suspension System		ممتص الصدمات
07.A Arms	FRONT LOWER ARM BUSH CUT	ازرع
08 Transmission Condition		الجير
08.A Road Test	NOT CHECK	فحص علي الطريق
08.B Visual Gear Box Condition	NOT CHECK & OIL LEAK	حالة الجير النظرى
08.C DIFFERENTIAL	FRONT DIFFERENTAIL OIL LEAK	الدفرنشل
08.D Propeller Shaft	CENTER PROPELLER SHAFT BOLT MISSING & LOOSE	ناقل الحركة
09 Wipers and Arms		المساحات
09.A Wiper Arm &Blade	NOT CHECK	ازرع المساحات والشفرات
10 Chassis Condition		الشاصي
10.A Chassis	RUSTY	الشاسيه

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate,
 Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.