



## TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	27 Apr 2022, 12:57:36
Transaction Number	91540581 (CC10006)	Queue Number	312309



Chassis Number	3N1AB7AP9FL644050
Engine Number	
Vehicle Class	Car
Manufacturer	Nissan
Model	Sentra
Model Year	2015
Color	Silver
Mileage	40163 Miles
Fuel Type	Petrol
No. Of Cylinders	4
Specification	USA Imported

DEFECT	REMARKS	
<b>01 Body</b>		<b>جسم المركبة</b>
01.A Fenders	FRONT BOTH SIDE REPLACED & REAR REPAINTED,PORTION REPAIRED	مدكار
01.B Doors	LEFT SIDE BOTH REPAINTED & FRONT RIGT SIDE PORTION REPAIRED,REPAINTED	أبواب
01.C Sign of front accident		وجود مؤشر لحادث في المقدمة
01.D Paint	BODY PORTION REPAIRED , REPAINTED & MINOR DENT SCRATCHES	الصبغ
01.E Bonnet	REPAIRED,REPAINTED,REFITTED	غطاء المحرك
01.F Other	FRONT BUMPER FRAME BULK HEAF FENDER FRAME RADIATOR SUPPORT REPAIRED	اخرى
<b>02 Tires and Rims Condition</b>		<b>الاطارات</b>
02.A Front Tyre	BOTH SIDE 2020	الاطار الامامي
02.B Rear Tyre	BOTH SIDE 2020	الاطار الخلفي
<b>03 Engine Condition</b>		<b>المحرك</b>
03.A Visual Engine Condition	REFITTED	حالة المحرك النظري
<b>04 Transmission Condition</b>		<b>الجير</b>
04.A Visual Gear Box	REFITTED	حالة الجير النظري

DEFECT	REMARKS	
Condition		
04.B Road Test	NOT CHECK	فحص علي الطريق
<b>05 Steering Condition</b>		<b>المقود</b>
05.A Tie Rod End	BOOT CRACKED	مؤخرة الرودادات
<b>06 Suspension System</b>		<b>ممتص الصدمات</b>
06.A Arms	FRONT LOWER ARM BUSH CRACKED	ازرع
<b>07 Seats Condition</b>		<b>المقاعد</b>
07.A Seat Condition	SEATS HAVE EXTRA COVER	حالة المقاعد
<b>08 Chassis Condition</b>		<b>الشاصي</b>
08.A Chassis	FRONT BOTH SIDE CHASSIS REPAIRED ,	الشاسيه
<b>09 Interior Condition</b>		<b>الحاله الداخليه</b>
09.A AC Condition	OK	المكيف

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.