



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	22 Sep 2022, 16:37:51
Transaction Number	86367519 (CC10006)	Queue Number	594731



Chassis Number	WBAJB3100HWA04914
Engine Number	
Vehicle Class	Car
Manufacturer	BMW
Model	540i
Model Year	2017
Color	Blue
Mileage	46032 Km
Fuel Type	Petrol
No. Of Cylinders	6
Specification	GCC Specification

DEFECT	REMARKS	
01 Transmission Condition		الجير
01.A Road Test	NOT CHECK	فحص علي الطريق
01.B Visual Gear Box Condition	OK	حالة الجير النظرى
02 Tires and Rims Condition		الاطارات
02.A Front Tyre	BOTH SIDE 2020	الاطار الامامي
02.B Rear Tyre	BOTH SIDE 2017 CRACKED , EXPIRED	الاطار الخلفي
03 Interior Condition		الحاله الداخليه
03.A AC Condition	OK	المكيف
04 Body		جسم المركبة
04.A Paint	BODY MINOR SCRATCHES	الصبغ
04.B Floor	UNDER BODY FULLY COVERED&VISIBLE AREA CHECK ONLY	الارضية
05 Chassis Condition		الشاسي
05.A Chassis	FULLY COVERED CHECKED VISIBLE AREA OK	الشاسيه
06 Engine Condition		المحرك
06.A Visual Engine Condition	OK	حالة المحرك النظرى



- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.