CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2936934
Transaction Date	03 Nov 2026, 12:51:05
Site Name	840 - Emirates Auctions
Transaction Number	26086886 (CC10013) (CC10011)



Vehicle Details

Chassis Number	5N1AA0NC5F*******
Specification	GCC Specification
Make	Nissan
Model	Armada
Model Year	2015
Color	White
Mileage	135373 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	8

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	FRONT BOTH SIDE REFITTED	مدكار
01.B Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENTS SCRATCHES,PORTION FADED RUSTY	الصبغ
01.C Doors	REAR RIGHT SIDE REFITTED	أبواب
01.D Rusty	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY	صدأ
01.E Floor	UNDER FLOOR BODY MOUNT RUBBER DRY CRACK	الارضية
01.F Bumper	MISALIGN PORTION DAMAGED	دعامية
01.G Bonnet	REFITTED	غطاء المحرك
01.H Trunk	AUTO NOT WORKING PROPERLY,REAR HANDLE DAMAGED	صندوق
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS FRAME DIRTY MUDDY GETTING RUSTY PORTION MINOR DENT	الشاسيه
03 Engine Condition		المحرك
03.A Mount	MOUNT BRACKET BOLT MISSING	كرسي
03.B Other	INNER COMPARTMENT ELECTRIC WIREING WORN OUT UNSAFE / UPPER COVER MISSING	اخري
03.C Engine Visual Condition	OIL PAN DENT , REFITTED , PARTS GETTING RUSTY	الحالة النظريه للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	PORTION DAMAGED	حالة المقاعد

Condition	Remarks	الحالة
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	REFITTED , PARTS GETTING RUSTY	الحالة النظريه للجير
05.B DIFFERENTIAL	FRONT MOUNT RUBBER CRACK	الدفرنشل
05.C Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2022 WORN OUT CRACKED	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2022 WORN OUT CRACKED	الاطار الخلفي
07 Lights		الاضاءة
07.A Head Light	LEFT SIDE LENS GETTING FADED INNER CHROME WORN OUT,RIGHT SIDE MINOR CRACK	الاضاءة الرئيسية
07.B Tail Light	MINOR CRACK	الضوء الخلفي
08 Suspension System		ممتص الصدمات
08.A Arms	ARM BUSHES DRY CRACK	ازرع
08.B Stabilizer Bar And Link Rod	BOOT CUT	عمود التوازن و مثبت عمود التوازن
09 Steering Condition		المقود
09.A Steering Oil	OIL LEAK	زيت المقود
09.B Steering Boot	BOOT CUT LEAK	ربلة المقود
09.C Tie Rod End	BOOT CUT	مؤخرة الرودات
09.D Axle	BOOT CUT	اكسلات
10 Interior Condition		الحاله الداخليه
10.A Other	CENTER CONSOLE BOX COVER PORTION CRACKED LOCK DAMAGED / INTERIOR PARTS GETTING RUSTY SIGN OF FLOODED	اخري
10.B Mirror	RIGHT SIDE LOOSE AUTO FOLDING,ADJUSTMENT NOT WORKING	المرايا
10.C AC Condition	OK,GRILL PORTION DAMAGED	المكيف
10.D Audio	LCD NOT WORKING,STEREO MODIFIED	صوتيات
10.E Odometer reading	CLUSTER PANEL COVER MINOR SCRATCHES	قراءة عداد المسافات
10.F Door Panel	PORTION WORN OUT	لوحة بطانة الباب
10.G Steering Wheel and control buttons	WORN OUT,HORN SWITCH MODIFIED	عجلة القيادة وازرار التحكم
10.H Sunroof	NOT WORKING	فتحت سقف
10.I Gear Shifting Lever	KNOB WORN OUT,SHIFT LOCK COVER MISSING	ذراع نقل السرعات
10.J Engine Start Button	REMOTE MISSING	زر تشغيل المحرك
11 Battery Condition		حالة البطارية
11.A Battery bracket	MISSING	حامل البطارية

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر **wecare@carscheck.ae**