



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	11 Dec 2021, 18:05:42
Transaction Number	43361996 (CC10006)	Queue Number	312309



Chassis Number	WBAKB2109BC419699
Engine Number	
Vehicle Class	Car
Manufacturer	BMW
Model	730
Model Year	2011
Color	White
Mileage	194190 Km
Fuel Type	Petrol
No. Of Cylinders	6
Specification	GCC Specification

DEFECT	REMARKS	
01 Body		جسم المركبة
01.A Fenders	REAR BOTH SIDE REPAIRED, REPAINTED & FRONT RIGHT SIDE REPAINTED	مدكار
01.B Paint	PORTION REPAIRED, REPAINTED & DENTS, SCRATCHES ON BODY	الصبغ
01.C Doors	REAR RIGHT SIDE REPAIRED & REPAINTED	أبواب
01.D Bumper	REPAINTED & MISALIGN	دعامية
01.E Bonnet	REPAINTED	غطاء المحرك
01.F Trunk	PORTION REPAIRED & REPAINTED	صندوق
01.G Floor	REAR BACK PANEL, SPARE WHEEL HOUSING , QUATER PANEL REPAIRED	الارضية
02 Interior Condition		الحالة الداخلية
02.A Roof Ceiling	PORTION LOOSED	بطانه السقف
02.B AC Condition	OK & REAR GRAIL PORTION DAMAGED	المكيف
02.C Dash Board	CONSOLE BOX COVER LEATHER CRACKED	لوحة القيادة
02.D Door Panel	PORTION CRACKED	لوحة بطانة الباب
03 Seats Condition		المقاعد
03.A Seat Condition	LEATHER CRACKED	حالة المقاعد

DEFECT	REMARKS	
04 Tires and Rims Condition		الاطارات
04.A Front Tyre	BOOT SIDE 2020	الاطار الامامي
04.B Rear Tyre	BOTH SIDE 2020 CRACKED	الاطار الخلفي
04.C Rims Condition	SCRATCHES	حالة الجنوط
05 Chassis Condition		الشاصي
05.A Chassis	VISABLE AREA OK	الشاسيه
05.B Chassis Extension	REAR RIGHT SIDE END MINOR BEND	تمديدات الشاسي
06 Engine Condition		المحرك
06.A Engine Condition	OIL LEAK & REFITTED	حالة المحرك
07 Transmission Condition		الجير
07.A Road Test	NOT CHECK	فحص علي الطريق
07.B DIFFERENTIAL	BUSHES CRACKED	الدفرنشل
07.C Propeller Shaft	RUBBER CRACKED	ناقل الحركة
07.D Gear Box	SIGN OF LEAK	الجير
08 Lights		الاضاءة
08.A Head Light	OK	الاضاءة الرئيسية
08.B Fog light	LENS FADED	كشاف الضباب

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

Test Certificate



Vehicle
Registration



X FAILED

Plate Details :	7 34926 Abu Dhabi Private		
Chassis No :	WBAKB2109BC419699		
Vehicle Make :	BMW		
Vehicle Model :	730		
Vehicle Class :	Light Vehicle		
Body Type :	SALOON		
Fuel :	Benzene		
Color :	White		
Drive Direction :	--		
Dimensions : (H x W x L) :	-- x -- x --		
Current Odometer :	194193 Kms.		
Origin :	Germany	Model Year :	2011
Gear Type :	Automatic	Engine Size :	4400 CC
Engine No :	08597570	Horse Power :	258
Axles No :	2	Cylinders :	6
No Of Doors :	4	No Of Seats :	5
G. V. W. :	Empty Weight : 1500 Kgs. 2000 Kgs.		

Certificate Number :	5-TAS-2021-15783709		
Inspection Date :	29-12-2021		
Certificate Print Date :	29-12-2021		
Services :	Registration Test		
Vehicle Testing Partner :	Tasjeel		
Vehicle Testing Center :	Tasjeel Al Aweer		
Total Time Taken :	17 min 57 sec		
Appointment Ref Number :	--		
Start Time :	10:18	End Time :	10:36
Lane :	01	Token No. :	109
Attempt :	2	Prints No. :	1

Inspection Findings

Defects	Issue	Severity
Arm, mounting, bushes change front right and rear both side arm bushes	Cracked, broken, bend arm	Major
Engine repair oil leak	Oil leaking continuously	Major
Shock Absorber repair front right side	Major leak	Major

Inspection Remarks:

REAR COMPARTMENT/CROSS MEMBER&FLOOR REPAIRED/ REAR RIGHT SIDE CHASSIS EXTENSION MINOR DENT/ FRONT&REAR BUMPER&BULKHEAD REPAIRED

Payment Details

Inspection Performed by 62439	Payment Method Cash	Transaction Number 15783709	Service Fees AED 70 Collected on 29/12/2021
Parking Slot No --	Service Name Registration Test	Attempt 2	Received by Hussain Basha Akeel

i This is to acknowledge the receipt of AED 70 (in words: Seventy Dirhams Only.), towards the above service.

i Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

تستخدم هذه الشهادة حصرا في العمليات الخاصة بالترخيص الفني للمركبة. لا يعتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلاف عملية ترخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص.

This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.

