



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	05 Sep 2021, 15:25:00
Transaction Number	60172565 (CC10007)	Queue Number	312309



Chassis Number	JN8FY15Y66X553313
Engine Number	
Vehicle Class	Car
Manufacturer	Nissan
Model	Patrol
Model Year	2006
Color	Silver
Mileage	148184

DEFECT

REMARKS

01 Body

جسم المركبة

01.A Fenders	BOTH SIDE REPAIRED & REPAINTED	مدكار
01.B Paint	PORTION REPAIRED, REPAINTED & DENTS, SCRATCHES ON BODY	الصبغ
01.C Doors	PORTION REPAIRED & REPAINTED	أبواب
01.D Rusty	UNDER BODY PARTS ,FLOORING, CHASSIS GETTING RUSTY	صدأ
01.E Floor	FRONT BOTH SIDE FLOOR , FENDER FRAME JOINT, WHEEL HOUSING REPAIRED & RE-JOINT (FRONT BODY JOINT)	الارضية
01.F Bumper	REPAINTED	دعامية
01.G Bonnet	REPLACED	غطاء المحرك
01.H Pillars	FRONT BOTH SIDE PILLAR, POST REPAIRED	القوائم
01.I Other	REAR QUATERPANEL, PILLAR, BACK PANEL REPAIRED OLD	اخرى

02 Chassis Condition

الشاسي

02.A Chassis	BOTH SIDE HEATED, REPAIRED & INNER BEND	الشاسيه
02.B Other	VIN NUMBER GETTING RUSTY	اخرى
02.C Chassis Extension	REAR BOTH SIDE , BODY MOUNT SLIGHTLY BEND	تعديلات الشاسي

03 Engine Condition

المحرك

03.A Mount	BUSHES CRACKED	كرسي
03.B Other	OIL LEAK	اخرى
03.C Modification	AIR FILTER MODIFIED	تعديلات

DEFECT	REMARKS	
04 Seats Condition		المقاعد
04.A Other	OK	اخرى
05 Transmission Condition		الجير
05.A Gear Box	OIL LEAK	الجير
05.B Gear Box Mount	BUSHES CRACKED	كرسي الجير
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2020	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2020	الاطار الخلفي
07 Wipers and Arms		المساحات
07.A Other	NOT CHECK	اخرى
08 Lights		الاضاءة
08.A Other	ALL NOT CHECK	اخرى
09 Exhaust System		نظام العادم
09.A Modification	HEADERS	تعديلات
09.B Other	WELDED & REPAIRED	اخرى
10 Brake Condition		الفرامل
10.A Caliber Brake	GETTING RUSTY	جهاز الفرامل
11 Suspension System		ممتص الصدمات
11.A Arms	FRONT BOTH SIDE LOWER ARMS & REAR CONTROL ARMS BUSHES CRACKED	ازرع
12 Steering Condition		المقود
12.A Tie Rod End	BUSHES CRACKED	مؤخرة الرودادات
13 Interior Condition		الاجزاء الداخلية
13.A Other	OK	اخرى
13.B Mirror	OK	المرايا
13.C AC Condition	NOT CHECK	المكيف

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.