



## TEST CERTIFICATE

Site Number	<b>840-Emirates Auctions</b>	Transaction Date	<b>20 Oct 2021, 17:45:01</b>
Transaction Number	<b>27691887 (CC10006)</b>	Queue Number	<b>312309</b>



Chassis Number	<b>6G1MP54H87L918173</b>
Engine Number	
Vehicle Class	<b>Car</b>
Manufacturer	<b>Chevrolet</b>
Model	<b>Caprice SS</b>
Model Year	<b>2007</b>
Color	<b>Black</b>
Mileage	<b>88205 Km</b>
Fuel Type	<b>Petrol</b>
No. Of Cylinders	<b>8</b>
Specification	<b>GCC Specification</b>

DEFECT	REMARKS	
<b>01 Body</b>		<b>جسم المركبة</b>
01.A Paint	BODY TOTALY REPAINTED,REPAIRED	الصبغ
01.B Rusty	UNDER BODY PART CHASSIS,FLOOR GETTING MINOR RUSTY	صدأ
01.C Trunk	INNER COVER MISSING	صندوق
01.D Fenders	REAR QUATER PANEL ,BACK PANELREPAIRED	مدكار
<b>02 Interior Condition</b>		<b>الحاله الداخليه</b>
02.A Door Panel	REAR DOOR HANDLE BROKEN ,LEATHER LOSE	لوحة بطانة الباب
02.B Dash Board	CONSOE BOX NOT DAMAGED,NOT OPENING &TRANSMISION CONSOLE BOX LOSE&LEFT FUSE BOX COVER MISSING	لوحة القيادة
02.C AC Condition	NOT WORKING &CENTER VENT LOSE&RIGHT GRILL MISSING	المكيف
02.D Audio	NOT WORKING	صوتيات
02.E Other	STEERING WHEEL WORNOUT	اخرى
<b>03 Seats Condition</b>		<b>المقاعد</b>
03.A Seat Condition	SIDE ADJUSTMENT COVER LOSE	حالة المقاعد
03.B Seat Belt	OK	حزام الأمان

DEFECT	REMARKS	
<b>04 Tires and Rims Condition</b>		<b>الاطارات</b>
04.A Rear Tyre	BOTH SIDE 2018 CRACKED	الاطار الخلفي
04.B Front Tyre	BOTH SIDE 2021	الاطار الامامي
04.C Rims Condition	RIMS HAVE SCRATCHES &DENTS	حالة الجنوط
04.D Other	NOISY FROM REAR LEFT WHEEL	اخرى
<b>05 Lights</b>		<b>الاضاءة</b>
05.A Fog light	LEFT COVER BROKEN	كشاف الضباب
05.B Head Light	LEFT HEAD LIGHT BRACKET BROKEN	الاضاءة الرئيسية
05.C Warning Light	WARNING ON IN DISPLAY	ضوء تحذير
05.D Indicator & Hazard light	HAZARD LIGHT NOT WORKING	الاشارات
<b>06 Engine Condition</b>		<b>المحرك</b>
06.A Engine Condition	OPEN,REFITIED,SIGN OF OIL WET.NOISY	حالة المحرك
06.B Smoke	WHITE SMOKE	دخان
<b>07 Transmission Condition</b>		<b>الجير</b>
07.A Road Test	NOT CHECK	فحص علي الطريق
07.B Gear Box	MINOR OIL LEAK	الجير
<b>08 Steering Condition</b>		<b>المقود</b>
08.A Steering Oil	OIL LEAK	زيت المقود
<b>09 Chassis Condition</b>		<b>الشاسي</b>
09.A Chassis	OK	الشاسيه
<b>10 Wipers and Arms</b>		<b>المساحات</b>
10.A Wiper Arm &Blade	WORN OUT	ازرع المساحات والشفرات
<b>11 Brake Condition</b>		<b>الفرامل</b>
11.A Break Pads	WEAR	سفايف الرامل
11.B Disc&Drum	GETTING MINOR RUSTY	دسك وطنابير الفرامل
11.C Other	BRAKE PADEL HARD AND BRAKE WEAK	اخرى
<b>12 Suspension System</b>		<b>ممتص الصدمات</b>
12.A Suspension Subframe	CHECK NOISY COMING FROM REAR WHEEL	

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate,



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

Car Check does not guarantee the vehicle's fitness for registration.