

Queue Number 2627798

Transaction Date 08 Aug 2026, 11:55:12

Site Name
840 - Emirates AuctionsTransaction Number
35222150 (CC10013) (CC10019)

Vehicle Details

Chassis Number	LJ12FKT36P*****
Specification	GCC Specification
Make	JAC
Model	J7
Model Year	2023
Color	White
Mileage	N/A NA
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
-----------	---------	--------

01 Body

جسم المركبة

01.A Fenders	FRONT BOTH SIDE REFITTED	مذكرار
01.B Paint	BODY PORTION REPAINTED, PORTION REPAIRED, MINOR DENTS & SCRATCHES, PORTION RUSTY, PORTION FADED, PORTION STICKER	الصبغ
01.C Rusty	UNDER BODY PARTS, SUSPENSION GETTING RUSTY	صدأ
01.D Floor	UNDER FLOOR MUDDY, PORTION DENTS	الارضية
01.E Bumper	MISALIGN, PORTION DAMAGED	دعامية
01.F Windshield	FRONT CRACKED	زجاج
01.G Bonnet	REFITTED	غطاء المحرك
01.H Vehicle Color	WHITE / BLACK	لون المركبة

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS MUDDY DIRTY PORTION GETTING RUSTY / FRONT RIGHT SIDE END BRACKET OPEN DETACHED	الشاسيه
--------------	--	---------

03 Engine Condition

المحرك

03.A Other	COMPARTMENT PART MISSING / FUSE BOX COVER DAMAGED / WIREING UNSAFE SIGN OF BURNING	اخرى
03.B Engine Visual Condition	ENGINE NOT START, ALL SYSTEM NOT CHECKED, REFITTED, OIL LEAK, PARTS RUSTY	الحالة النظرية للمحرك

04 Transmission Condition

الجير

Condition	Remarks	الحالة
04.A Gear Box Visual Condition	NOT CHECKED,REFITTED,OIL LEAK,PARTS RUSTY	الحالة النظرية للجير
04.B Road Test	NOT CHECKED	فحص علي الطريق
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	DAMAGED CRACKED	الاطار الامامي
05.B Rear Tyre	DAMAGED CRACKED	الاطار الخلفي
05.C Rims Condition	REPAINTED	حالة الجنوط
06 Lights		الاضاءة
06.A Head Light	LENS FADED, ALL LIGHTS NOT CHECKED,DAMAGED	الاضاءة الرئيسية
07 Brake Condition		الفرامل
07.A Disc&Drum	RUSTY	دسك وطنابير الفرامل
08 Suspension System		ممتص الصدمات
08.A Shock Absorber	LEAK	ممتص الصدمات
08.B Arms	ARM BUSHES DRY CRACK	ازرع
09 Interior Condition		الحالة الداخلية
09.A Other	INTERIOR PARTS GETTING FADED WATER FLOODED	اخرى
09.B Mirror	CENTER MISSING	المرايا
09.C AC Condition	NOT CHECKED	المكيف
09.D Dash Board	DAMAGED	لوحة القيادة
09.E Roof Ceiling	MODIFIED	بطانة السقف
09.F Odometer reading	CLUSTER FADED WORN OUT NOT CHECKED	قراءة عداد المسافات
09.G Door Panel	PORTION DAMAGED	لوحة بطانة الباب
09.H Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
09.I Gear Shifting Lever	KNOB WORN OUT	ذراع نقل السرعات
09.J Engine Start Button	BUTTON DAMAGED	زر تشغيل المحرك

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

For complaints and inquiries reach out to us on
wecare@carscheck.ae

للشكاوي والمقترحات يمكنك التواصل معنا عبر
wecare@carscheck.ae