CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2972324
Transaction Date	11 Nov 2026, 13:47:52
Site Name	840 - Emirates Auctions
Transaction Number	67667373 (CC10008) (CC10011)



Vehicle Details

Chassis Number	1GTN2TE00B*******
Specification	Imported
Make	GMC
Model	Sierra
Model Year	2011
Color	Black
Mileage	294744 Miles
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	8

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	REFITTED MODIFIED,RIGHT SIDE STRIP PORTION CRACK MISALIGN	مدكار
01.B Paint	BODY REPAIRED REPAINTED,MINOR DENTS SCRATCHES,PORTION RUSTY GETTING FADED	الصبغ
01.C Doors	REFITTED	أبواب
01.D Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.E Bumper	MODIFIED	دعامية
01.F Bonnet	REFITTED,SHOCK WEAK	غطاء المحرك
01.G Pillars	B/PILLAR OUTER PANEL REPAINTED PORTION REPAIRED,INNER COVER LOOSE	القوائم
01.H Trunk	CABIN MODIFIED WITH EXTRA STRIP,TALGATE LOCK HANDLE PANEL COVER ,STRIP MISSING	صندوق
01.I Sign of front accident		وجود مؤشر لحادث في المقدمة
01.J Sign of side accident		وجود مؤشر لحادث في الجانب
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS REPAIRED BEND ,RUSTY	الشاسيه
02.B Chassis Number	VIN ON FRAME RUSTY NOT VISIBLE ,LEFT SIDE DOOR STICKER REMOVED ,VIN CHECKED ON WINDSHIELD ONLY	رقم القاعدة
03 Engine Condition		المحرك
03.A Smoke	BLACK	دخان
03.B Engine Visual Condition	MINOR OIL LEAK ,REFITTED ,PARTS GETTING RUSTY	الحالة النظريه للمحرك

Condition	Remarks	الحالة
04 Seats Condition		المقاعد
04.A Seat Condition	EXTRA COVER,RIGHT SIDE SEAT ADJUSTMENT NOT WORKING PROPERLY HANDLE PORTION DAMAGED LOOSE,SIDE COVER PART MISSING	حالة المقاعد
05 Exhaust System		نظام العادم
05.A Modification	MODIFIED	تعديلات
05.B Catalytic Converter	MISSING	دبة البيئة
06 Transmission Condition		الجير
06.A Gear Box Visual Condition	REFITTED ,PARTS GETTING RUSTY	الحالة النظريه للجير
06.B Road Test	NOT CHECK	فحص علي الطريق
06.C Four Wheel Drive	NOT WORKING	الدفع الرباعي
07 Tires and Rims Condition		الاطارات
07.A Front Tyre	BOTH SIDE 2021 CRACK EXPIRED	الاطار الامامي
07.B Rear Tyre	BOTH SIDE 2021 CRACK EXPIRED	الاطار الخلفي
08 Lights		الاضاءة
08.A Head Light	RIGHT SIDE HIGH BEAM NOT WORKING	الاضاءة الرئيسية
08.B Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
09 Steering Condition		المقود
09.A Steering Oil	OIL LEAK	زيت المقود
09.B Steering Boot	BOOT LOOSE	ربلة المقود
10 Interior Condition		الحاله الداخليه
10.A Other	INTERIOR PARTS RUSTY ,SIGN OF FLOODED ,CENTER CONSOLE BOX DAMAGED	اخري
10.B Mirror	BOTH SIDE ADJUSTMENT NOT WORKING LEFT SIDE INNER COVER MISSING,CENTER FADED LOOSE	المرايا
10.C AC Condition	OK	المكيف
10.D Power Window Switch And Glass	LEFT SIDE SWITCH LOOSE	مفتاح النافذه و الزجاج
10.E FLoor Matting	EXTRA COVER	فرش الأرضيه
10.F Audio	MODIFIED LCD	صوتيات
10.G Dash Board	DAMAGED EXTRA COVER MODIFIED SWITCH	لوحة القياده
10.H Roof Ceiling	PORTION LOOSE,DIRTY	بطانه السقف
10.I Door Panel	PORTION DAMAGED	لوحة بطانة الباب
10.J Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر **wecare@carscheck.ae**