CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2963010
Transaction Date	09 Nov 2026, 15:18:08
Site Name	840 - Emirates Auctions
Transaction Number	38317532 (CC10009) (CC10019)



Vehicle Details

Chassis Number	1GNEK13R2W*******
Specification	Imported
Make	Chevrolet
Model	Suburban
Model Year	1998
Color	Blue
Mileage	175984 Miles
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	8

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	FRONT BOTH SIDE REFITTED	مدكار
01.B Paint	BODY TOTALY REPAINTED,PORTION REPAIRED MINOR DENT SCRATCHES,PORTION FADED	الصبغ
01.C Rusty	UNDER BODY PARTS CHASSIS SUSPENSION GETTING RUSTY APPLIED THICK RUST PROOFED	صدأ
01.D Floor	FLOOR CHASSIS THICK RUST PROOFED, NOT VISIBLE, BODY MOUNT BEND	الارضية
01.E Bonnet	REFITTED	غطاء المحرك
01.F Trunk	NOT OPEN	صندوق
01.G Vehicle Model	TAHO	طراز المركبة
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS FRAME SUBFRAME BEND , COMPLELEY THICK RUST PROOFED GETTING RUSTY	الشاسيه
02.B Chassis Number	NOT VISIBLE	رقم القاعدة
03 Engine Condition		المحرك
03.A Engine Visual Condition	MINOR OIL LEAK OPEN REFITTEDGETTING RUSTY SHAKING, WIRING LOOSE	الحالة النظريه للمحرك
04 Seats Condition		المقاعد
04.A Seat Belt	NOT WORKING	حزام الأمان
04.B Seat Condition	EXTRA COVER	حالة المقاعد
05 Transmission Condition		الجير

Condition	Remarks	الحالة
05.A Gear Box Visual Condition	OPEN REFITTED GETTING RUSTY SUMB MINOR DENT	الحالة النظريه للجير
05.B Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2023	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2023	الاطار الخلفي
07 Lights		الاضاءة
07.A Head Light	NOT WORKING ,SWITCH WORN OUT MELTED	الاضاءة الرئيسية
07.B Fog light	LENS FADED	كشاف الضباب
08 Interior Condition		الحاله الداخليه
08.A Other	INETRIOR PARTS GETTING RUSTY	اخري
08.B Mirror	CENTER MIRROR PORTION LOOSE	المرايا
08.C AC Condition	OK	المكيف
08.D Power Window Switch And Glass	REAR BOTH SIDE NOT WORKING PROPERLY.SWITCH BUTTON PORTION DAMAGED	مفتاح النافذه و الزجاج
08.E Audio	MISSING	صوتيات
08.F Dash Board	PORTION CRACKED DAMAGED,EXTRA COVER	لوحة القياده
08.G Roof Ceiling	PORTION LOOSE	بطانه السقف
08.H Sun Visor	BOTH SIDE COVER MIRROR MISSING	حاجب الشمس
08.I Door Panel	PORTION CRACKED	لوحة بطانة الباب

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae