CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2899662
Transaction Date	29 Oct 2026, 14:45:47
Site Name	840 - Emirates Auctions
Transaction Number	40058569 (CC10010) (CC10011)



Vehicle Details

Chassis Number	1B3CB2HA9A*******
Specification	GCC Specification
Make	Dodge
Model	Caliber
Model Year	2010
Color	Silver
Mileage	335655 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	FRONT LEFT SIDE REFITTED	مدكار
01.B Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENTS SCRATCHES,PORTION FADED RUSTY	الصبغ
01.C Rusty	UNDER BODY SUSPENSION PARTS RUSTY	صدأ
01.D Floor	UNDER FLOOR PORTION DENT	الارضية
01.E Bumper	MISALIGN PORTION CRACKED	دعامية
01.F Bonnet	REFITTED	غطاء المحرك
01.G Trunk	NOT OPEN	صندوق
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS COMPLETE COVERED ,OILY MUDDY NOT VISIBLE PROPERLY,CHECKED ONLY VISIBLE AREA /OK.	الشاسيه
03 Engine Condition		المحرك
03.A Engine Visual Condition	ENGINE NOT START ALL SYSTEM NOT CHECKED REFITTED OIL LEAK PARTS RUSTY.	الحالة النظريه للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	DIRTY,DRIVER SEAT NECK REST DAMAGED	حالة المقاعد
05 Transmission Condition		الجير

Condition	Remarks	الحالة
05.A Gear Box Visual Condition	NOT CHECKED REFITTED OIL LEAK PARTS RUSTY	الحالة النظريه للجير
05.B Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2022 CRACK,LEFT SIDE PUNCTURE	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2022 CRACK	الاطار الخلفي
07 Lights		الاضاءة
07.A Head Light	LENS FADED ALL LIGHT NOT CHECK	الاضاءة الرئيسية
08 Brake Condition		الفرامل
08.A Disc&Drum	PARTS RUSTY	دسك وطنابير الفرامل
09 Suspension System		ممتص الصدمات
09.A Shock Absorber	LEAK	ممتص الصدمات
09.B Arms	BUSHES CRACKED	ازرع
10 Steering Condition		المقود
10.A Steering Boot	CUT	ربلة المقود
10.B Steering Box	OIL LEAK	جهاز المقود
11 Interior Condition		الحاله الداخليه
11.A Other	INTERIOR DUSTY DIRTY,RUSTY SIGN PF FLOODED.	اخري
11.B Mirror	CENTER GETTING FADED	المرايا
11.C AC Condition	NOT CHECK	المكيف
11.D Audio	LCD DAMAGED	صوتيات
11.E Sun Visor	LEFT SIDE BRACKET DAMAGED MIRROR MISSING,RIGHT SIDE MIRROR STUCK IN COVER	حاجب الشمس
11.F Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
11.G Gear Shifting Lever	KNOB WORN OUT MELTED	ذراع نقل السرعات
11.H Engine Start Button	REMOTE DAMAGED,KEY STUCK IN SWITCH	زر تشغيل المحرك
12 Battery Condition		حالة البطارية
12.A Battery Condition	MISSING	حالة البطارية

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة،
كما لا تضمن بموجب هذه الشهادة صلاحية المركبة
.للتسجيل من عدمه

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae