CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2934082
Transaction Date	02 Nov 2026, 14:28:51
Site Name	840 - Emirates Auctions
Transaction Number	55015071 (CC10010) (CC10010)



Vehicle Details

Chassis Number	JTDBT92398*******
Specification	GCC Specification
Make	Toyota
Model	Yaris
Model Year	2008
Color	White
Mileage	N/A Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		**جسم المركبة**
01.A Fenders	REPAINTED PORTION REPAIRED	مدكار
01.B Paint	BODY PORTION REPAINTED, PORTION REPAIRED DENTS, SCRATCHES , PORTION RUSTY, PORTION FADED	الصبغ
01.C Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY.	صدأ
01.D Floor	UNDER FLOOR PORTION DENT ,MUDDY.,	الارضية
01.E Bumper	MISALIGN ,SCRATCHES PORTION DAMAGED	دعامية
01.F Bonnet	REPAINTED	غطاء المحرك
01.G Trunk	NOT OPEN	صندوق
01.H Sign of front accident	FRONT BUMPER FRAME , RADIATOR SUPPORT BULK HEAD,FENDER FRAME CROSS MEMBER REPAIRED.	وجود مؤشر لحادث في المقدمة
02 Chassis Condition		**الشاصي**
02.A Chassis	FRONT CHASSIS END DENT ,CRASH BOX REPAIRED GETTING RUSTY.	الشاسيه
03 Engine Condition		**المحرك**
03.A Engine Visual Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED ,REFITTED OIL LEAK,PARTS RUSTY	الحالة النظريه للمحرك
04 Transmission Condition		**الجير**
04.A Gear Box Visual Condition	NOT CHECKED ,REFITTED,OIL LEAK ,COMPONENT PARTS RUSTY .	الحالة النظريه للجير
04.B Road Test	NOT CHECKED.,	فحص علي الطريق

Condition	Remarks	الحالة
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	BOTH SIDE 2021 EXPIRED CRACKED.	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2021 EXPIRED CRACKED.	الاطار الخلفي
06 Lights		الاضاءة
06.A Head Light	LENS FADED, ALL LIGHTS NOT CHECK	الاضاءة الرئيسية
06.B Tail Light	PORTION CRACKED .	الضوء الخلفي
07 Brake Condition		الفرامل
07.A Disc&Drum	RUSTY.	دسك وطنابير الفرامل
08 Suspension System		ممتص الصدمات
08.A Suspension Subframe	RUSTY BHOLE WEAK .	
08.B Shock Absorber	LEAK	ممتص الصدمات
08.C Arms	BUSHES CUT	ازرع
09 Steering Condition		المقود
09.A Steering Boot	CUT	ربلة المقود
09.B Steering Box	OIL LEAK	جهاز المقود
10 Interior Condition		الحاله الداخليه
10.A Other	INTERIOR PARTS GETTING RUSTY ,SIGN OF FLOODED	اخري
10.B Mirror	LOOSE ,FADED	المرايا
10.C AC Condition	NOT CHECKED.	المكيف
10.D Dash Board	PORTION LOOSE	لوحة القياده
10.E Roof Ceiling	GRAB HANDLE MISSING	بطانه السقف
10.F Odometer reading	NOT CHECKED.	قراءة عداد المسافات
10.G Door Panel	WORN OUT PORTION LOOSE	لوحة بطانة الباب
10.H Steering Wheel and control buttons	WORN OUT .	عجلة القيادة وازرار التحكم
10.I Gear Shifting Lever	KNOB WORN OUT.	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة،
كما لا تضمن بموجب هذه الشهادة صلاحية المركبة
.للتسجيل من عدمه

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae