



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	08 Dec 2022, 12:30:27
Transaction Number	15296444 (CC10009)	Queue Number	637589



Chassis Number	SALLSAAD4DA769865
Engine Number	
Vehicle Class	Car
Manufacturer	Range Rover
Model	Sport
Model Year	2013
Color	Black
Mileage	87137 Km
Fuel Type	Petrol
No. Of Cylinders	8
Specification	GCC Specification

DEFECT	REMARKS	
01 Interior Condition		الحاله الداخليه
01.A AC Condition	OK	المكيف
02 Transmission Condition		الجير
02.A Visual Gear Box Condition	OIL LEAK REFITTED JERKING	حالة الجير النظرى
02.B DIFFERENTIAL	REFITTED	الدفرنشيل
02.C Gear Box Mount	MOUNT RUBBER CRACKED	كرسي الجير
02.D Propeller Shaft	REFITTED	ناقل الحركة
02.E Road Test	NOT CHECKED	فحص علي الطريق
03 Body		جسم المركبة
03.A Bonnet	SHOCK NOT WORKING	غطاء المحرك
03.B Paint	MINOR DENT SCRATCHES ON BODY , PORTION FIBER	الصيغ
03.C Trunk	FIBER PAINT CANNOT BE CHECKED	صندوق
04 Suspension System		ممتص الصدمات
04.A Ball Joint	BOOT CUT	مفصل كروي
04.B Arms	LOWER ARM BUSHES CRACKED	ازرع

DEFECT	REMARKS	
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	BOTH SIDE 2021	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2021	الاطار الخلفي
06 Steering Condition		المقود
06.A Tie Rod End	BOOT CUT	مؤخرة الرودادات
07 Engine Condition		المحرك
07.A Mount	MOUNT RUBBER CRACKED	كرسي
07.B Visual Engine Condition	ABNORMAL NOISY, OIL LEAK REFITTED, SHAKING	حالة المحرك النظري
08 Chassis Condition		الشاسي
08.A Chassis	CHECKED VISIBLE AREA OK	الشاسيه

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.