





Test Certificate

Site Number	: 840-EMIRATES AUCTION	Plate Code	: 0
Transaction Number	: 20071036	Plate Category	: PRIVATE
Transaction Date	: 28 JUN 2020 12:41:31	Plate Number	: 248232 EA
Queue Number	: 190277	Import Doc. Ref.	:
Chassis Number	: WBAFE41069L248232	Manufacturer/Model	: BMW/X5
Engine Number	:	Model Year	: 2009
Vehicle Class	: LIGHT VEHICLE	Vehicle Color	: BLACK
Service / Indicator	: DSC AUCTION		

Statement of Vehicle Condition

Defect	Result	Remarks
AUTOMATIC TEST:		
13 Brake System		الفرامل
13.04 - Brake Test	Passed	فحص الفرامل
14 Exhaust Gas Test		الغاز العادم والكربون
14.01 - Exhaust Gas Test	Passed	فحص الغاز العادم-الكربون
16 Side Slip Test		فحص ميزانية الاطارات
16.01 - Side Slip Test	Passed	فحص ميزانية الاطارات
VISUAL TEST:		
02 Steering And Suspension System		عجلة القيادة ونظام التوصيلات
02.11 - Shock Absorbers		مخمد الصدمات
02.12 - Transmission Shaft, Flange Or Joint		عمود التعشيق
02.15 - Suspension Crack Or Bend, Bushes		التوصيلات
04 Tires Rims		الاطارات والعجلات
04.01 - Front Left And Right Hands Tires		الاطارات الامامية
04.07 - Rims		الرنجات
05 Body		الهيكل
05.02 - Paint		الصيغ
05.03 - Doors		الابواب
05.09 - Front And Rear Windshields		الزجاج الامامي والخلفي
06 General Items		الاشياء العامة
06.14 - Transmission Condition		حالة ناقل الحركة
06.16 - Engine Condition, Smoke		حالة المحرك - الدخان
07 Remarks		ملاحظات
07.04 - Others		ملاحظات اخرى
09 Auction		الفحص الكامل
09.06 - Chassis Ok	OK	الشاصي جيد
09.16 - Sign Of Side Accident		أثر حادث في جوانب المركبة
09.25 - Body Repainted		أثر صيغ في المركبة

The Test Certificate Shows the test Result at the time of inspection only.



Test Certificate

Site Number	: 840-EMIRATES AUCTION	Plate Code	: 0
Transaction Number	: 20071036	Plate Category	: PRIVATE
Transaction Date	: 28 JUN 2020 12:41:31	Plate Number	: 248232 EA
Queue Number	: 190277	Import Doc. Ref.	:
Chassis Number	: WBAFE41069L248232	Manufacturer/Model	: BMW/X5
Engine Number	:	Model Year	: 2009
Vehicle Class	: LIGHT VEHICLE	Vehicle Color	: BLACK
Service / Indicator	: DSC AUCTION		

Statement of Vehicle Condition