CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2934085
Transaction Date	03 Nov 2026, 17:00:03
Site Name	840 - Emirates Auctions
Transaction Number	61606278 (CC10026) (CC10026)



Vehicle Details

Chassis Number	WVGBC27P1C*******
Specification	GCC Specification
Make	Volkswagen
Model	Touareg
Model Year	2012
Color	Black
Mileage	N/A NA
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition	Remarks	الحالة
01 Body		**جسم المركبة**
01.A Fenders	FRONT BOTH SID REFITTED	مدكار
01.B Paint	BODY REPAINTED , PORTION REPAIRED, DENTS, SCRATCHES , PORTION FADED	الصبغ
01.C Rusty	UNDER BODY PARTS , SUSPENTION GETTING RUSTY , SIGN OF FLOODED	صدأ
01.D Floor	UNDER FLOOR PORTION DENTS, MUDDY	الارضية
01.E Bumper	MISALIGN , TOW HOOK COVER MISSING	دعامية
01.F Bonnet	REPAINTED PORTION REPAIRED , MISALIGN	غطاء المحرك
01.G Door Handle &Lock	FRONT LEFT SIDE OUTER LOCK COVER DAMAGE	مقابض الأبواب والأقفال
02 Chassis Condition		**الشاصي**
02.A Chassis	OK	الشاسيه
03 Engine Condition		**المحرك**
03.A Engine Visual Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED, PARTS REFITTED GETTING RUSTY , SIGN OF OIL WET	الحالة النظريه للمحرك
04 Seats Condition		**المقاعد**
04.A Seat Condition	PORTION WORN OUT	حالة المقاعد
05 Transmission Condition		**الجير**
05.A Gear Box Visual Condition	NOT CHECKED, PARTS REFITTED GETTING RUSTY , SIGN OF OIL WET	الحالة النظريه للجير

Condition	Remarks	الحالة
05.B Road Test	NOT CHECK	فحص علي الطريق
06 Tires and Rims Condition		**الاطارات**
06.A Front Tyre	BOTH SIDE 2024	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2024	الاطار الخلفي
06.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
07 Lights		**الاضاءة**
07.A Head Light	LENS FADED, ALL LIGHTS NOT CHECKED	الاضاءة الرئيسية
08 Suspension System		**ممتص الصدمات**
08.A Arms	BUSHES CRACK	ازرع
08.B Stabilizer Bar And Link Rod	BOOT CRACK	عمود التوازن و مثبت عمود التوازن
09 Interior Condition		**الحاله الداخليه**
09.A Other	CENTER CONSOLE BOX COVER PORTION DAMAGE	اخري
09.B AC Condition	NOT CHECK	المكيف
09.C FLoor Matting	EXTRA COVER , DIRTY	فرش الأرضيه
09.D Roof Ceiling	PORTION WORN OUT	بطانه السقف
09.E Door Panel	PORTION DAMAGE	لوحة بطانة الباب
09.F Steering Wheel and control buttons	PORTION WORN OUT	عجلة القيادة وازرار التحكم
09.G Gear Shifting Lever	PORTION WORN OUT , DUST COVER PORTION DAMAGE	ذراع نقل السرعات
10 Engine Cooling System		**نظام تبريد المحرك**
10.A Coolant tank	EMPTY	خزان التبريد

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae