CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2934013
Transaction Date	05 Nov 2026, 16:44:47
Site Name	840 - Emirates Auctions
Transaction Number	57300251 (CC10013) (CC10013)



Vehicle Details

Chassis Number	JN8AZ08W78*******
Specification	GCC Specification
Make	Nissan
Model	Murano
Model Year	2008
Color	Maroon
Mileage	N/A NA
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Paint	BODY PORTION REPAINTED , DENTS, SCRATCHES , PORTION GETTING FADED & RUSTY	الصبغ
01.B Rusty	UNDER BODY PARTS ,SUSPENSION GETTING RUSTY	صدأ
01.C Floor	UNDER FLOOR PORTION DENTS, MUDDY	الارضية
01.D Bumper	MISALIGN, PORTION DAMAGED	دعامية
01.E Trunk	NOT OPEN FIBER / INNER SAFETY COVER MISSING	صندوق
01.F Fuel Tank	DENT	خزان الوقود
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS COVERED MUDDY DIRTY PORTION GETTING RUSTY MINOR DENT	الشاسيه
03 Engine Condition		المحرك
03.A Engine Visual Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED REFITTED OIL LEAK OIL PAN DENT . PARTS RUSTY KEY MISSING	الحالة النظريه للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	REAR MISSING	حالة المقاعد
05 Exhaust System		نظام العادم
05.A Other	DENT	اخري
06 Transmission Condition		الجير

Condition	Remarks	الحالة
06.A Gear Box Visual Condition	NOT CHECKED REFITTED OIL LEAK PARTS RUSTY	الحالة النظريه للجير
06.B Road Test	NOT CHECKED	فحص علي الطريق
07 Tires and Rims Condition		الاطارات
07.A Front Tyre	2023 DRY CRACK	الاطار الامامي
07.B Rear Tyre	2023 DRY CRACK	الاطار الخلفي
08 Lights		الاضاءة
08.A Head Light	LENS FADED, ALL LIGHTS NOT CHECKED	الاضاءة الرئيسية
09 Brake Condition		الفرامل
09.A Disc&Drum	RUSTY	دسك وطنابير الفرامل
10 Suspension System		ممتص الصدمات
10.A Shock Absorber	LEAK	ممتص الصدمات
10.B Arms	LOWER ARM BUSHES CUT	ازرع
10.C Ball Joint	BOOT CUT	مفصل كروي
10.D Stabilizer Bar And Link Rod	BOOT CUT	عمود التوازن و مثبت عمود التوازن
11 Steering Condition		المقود
11.A Tie Rod End	BOOT CUT	مؤخرة الرودات
12 Interior Condition		الحاله الداخليه
12.A Other	INTERIOR PARTS RUSTY,SIGN OF FLOODED	اخري
12.B AC Condition	NOT CHECKED	المكيف
12.C Roof Ceiling	PORTION WORN OUT	بطانه السقف
12.D Sun Visor	LEFT MISSING RIGHT LOOSE	حاجب الشمس
12.E Odometer reading	NOT CHECKED	قراءة عداد المسافات
12.F Door Panel	PORTION WORN OUT DAMAGED	لوحة بطانة الباب
12.G Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
12.H Gear Shifting Lever	KNOB WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة،
كما لا تضمن بموجب هذه الشهادة صلاحية المركبة
.للتسجيل من عدمه

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae