

Queue Number 2866275

Transaction Date 15 Oct 2026, 16:43:33

Site Name
840 - Emirates AuctionsTransaction Number
63808843 (CC10013) (CC10011)

Vehicle Details

Chassis Number	W1K3G4EB9M*****
Specification	Imported
Make	Mercedes
Model	A220
Model Year	2021
Color	White
Mileage	148785 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	FRONT BOTH SIDE REFITTED	مدكار
01.B Paint	BODY REPAINTED PORTION REPAIRED, EXCEPT ROOF TRUNK, MINOR DENT SCRATCHES, PORTION FADED	الصبغ
01.C Doors	FRONT BOTH SIDE REFITTED	أبواب
01.D Rusty	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY	صدأ
01.E Floor	UNDER FLOOR COMPLETELY COVERED / FOR FULL INSPECTION MAKE STEAM WASH & REMOVE INNER FENDER UNDER ENGINE COVER FOR RECHECK	الارضية
01.F Bumper	MISALIGN, PORTION CRACK	دعامية
01.G Bonnet	REFITTED, STAY SHOCK NOT WORKING	غطاء المحرك
01.H Pillars	RIGHT SIDE A/PILLAR ROCKER PANEL REPAIRED	القوائم
01.I Trunk	LOGO LETTER MISSING	صندوق
01.J Sign of front accident	FRONT ASSEMBLY REFITTED	وجود مؤشر لحادث في المقدمة
01.K Sign of side accident		وجود مؤشر لحادث في الجانب

02 Chassis Condition

الشاسي

02.A Chassis	FRONT LEFT SIDE CHASSIS END REPAIRED	الشاسيه
02.B Chassis Number	VIN AREA DIRTY CHECK DOOR POST STICKER	رقم القاعدة

03 Engine Condition

المحرك

03.A Engine Visual Condition	OIL LEAK DRIPPING, OPEN REFITTED, PARTS GETTING RUSTY	الحالة النظرية للمحرك
------------------------------	---	-----------------------

Condition	Remarks	الحالة
04 Transmission Condition		الجير
04.A Gear Box Visual Condition	OIL LEAK , REFITTED , PARTS GETTING RUSTY	الحالة النظرية للجير
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	LEFT SIDE 2026,RIGHT 2025	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2023 CRACKED	الاطار الخلفي
05.C Rims Condition	MINOR DENTS SCRATCHES	حالة الجنوط
06 Suspension System		ممتص الصدمات
06.A Arms	ARM BUSHES DRY CRACK	ازرع
06.B Other	SUSPENSION PARTS REFITTED	اخرى
07 Interior Condition		الحالة الداخلية
07.A Other	INTERIOR PARTS GETTING RUSTY	اخرى
07.B AC Condition	OK	المكيف
07.C Power Window Switch And Glass	NOT WORKING PROPERLY,LOCK SWITCH STUCK NOT WORKING	مفتاح النافذه و الزجاج
07.D Audio	CENTER PANEL SWITCH PORTION FADED	صوتيات
07.E Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
07.F Sunroof	NOT WORKING	فتحت سقف

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on wecare@carscheck.ae

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae