CAR CHECK

شهادة فحص مركبة
**Vehicle Test Certificate**

| | |
|---|---|
| Queue Number | 3007851 |
| Transaction Date | 19 Nov 2026, 13:40:30 |
| Site Name | 840 - Emirates Auctions |
| Transaction Number | 10153553 (CC10009) (CC10019) |




**Vehicle Details**

| | |
|---|---|
| Chassis Number | JTHBN30F71******* |
| Specification | Imported |
| Make | Lexus |
| Model | LS 430 |
| Model Year | 2001 |
| Color | Silver |
| Mileage | 464867 Miles |
| Fuel Type | Petrol |
| Transmission Type | |
| No. Of Cylinders | 8 |

| Condition | Remarks | الحالة |
|---|---|---|
| **01 Body** | | جسم المركبة |
| 01.A Fenders | FRONT BOTH SIDE REFITTED | مدكار |
| 01.B Paint | BODY PORTION REPAINTED,PORTION REPAIRED MINOR DENT SCRATCHES,PORTION FADED,PORTION RUSTY | الصبغ |
| 01.C Doors | RIGHT SIDE REFITTED | أبواب |
| 01.D Rusty | UNDER BODY PARTS GETTING RUSTY | صدأ |
| 01.E Floor | FLOOR CHASSIS COMPLETELY RUST PROOFED, MUDDY DIRTY OILY PORTION DENT | الارضية |
| 01.F Bonnet | REFITTED | غطاء المحرك |
| 01.G Pillars | RIGHT SIDE B/ PILLAR ROCKER PANEL REPAIRED | القوائم |
| 01.H Fuel Tank | RIGHT SIDE DENT | خزان الوقود |
| 01.I Sign of front accident | FRONT BUMPER FRAME BULK HEAD REPAIRED | وجود مؤشر لحادث في المقدمة |
| **02 Chassis Condition** | | الشاصي |
| 02.A Chassis | FRONT RIGHT SIDE CHASSIS LOWER JOINT AREA DENT, BOTH SIDE OILY | الشاسيه |
| **03 Engine Condition** | | المحرك |
| 03.A Smoke | BLACK | دخان |
| 03.B Engine Visual Condition | OIL LEAK OPEN REFITTED GETTING RUSTY, SHAKING | الحالة النظريه للمحرك |
| **04 Seats Condition** | | المقاعد |
| 04.A Seat Condition | EXTRA COVER | حالة المقاعد |

| Condition | Remarks | الحالة |
|---|---|---|
| **05 Transmission Condition** | | الجير |
| 05.A Gear Box Visual Condition | OIL LEAK OPEN REFITTED, JERKING | الحالة النظريه للجير |
| 05.B Road Test | NOT CHECKED | فحص علي الطريق |
| **06 Tires and Rims Condition** | | الاطارات |
| 06.A Front Tyre | BOTH SIDE 2025 | الاطار الامامي |
| 06.B Rear Tyre | BOTH SIDE 2025 | الاطار الخلفي |
| **07 Lights** | | الاضاءة |
| 07.A Head Light | LENS FADED | الاضاءة الرئيسية |
| 07.B Tail Light | RIGHT SIDE PORTION CRACKED | الضوء الخلفي |
| **08 Suspension System** | | ممتص الصدمات |
| 08.A Other | SUSPENSION REFITTED | اخري |
| **09 Interior Condition** | | الحاله الداخليه |
| 09.A Other | INETRIOR PARTS GETTING RUSTY | اخري |
| 09.B Mirror | RIGHT SIDE FOLDING ADJUSTMENT NOT WORKING | المرايا |
| 09.C AC Condition | OK | المكيف |
| 09.D Roof Light | CENTER BOX LOCK DAMAGED | أنارة السقف |
| 09.E Power Window Switch And Glass | FRONT RIGHT SIDE GLASS PORTION CRACKED | مفتاح النافذه و الزجاج |
| 09.F Dash Board | PORTION WORN OUT PORTION BULGE | لوحة القياده |
| 09.G Sunroof | NOT WORKING | فتحت سقف |
| 09.H Gear Shifting Lever | GEAR LOCK COVER MISSING & DUST COVER DAMAGED | ذراع نقل السرعات |
| **10 Battery Condition** | | حالة البطارية |
| 10.A Battery bracket | MISSING | حامل البطارية |

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
**carcheck.ae/certificate**

## Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

## الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
**wecare@carscheck.ae**