



TEST CERTIFICATE

Site Number **840-Emirates Auctions** Transaction Date **23 May 2023, 16:59:56**
 Transaction Number **97778137 (CC10008)** Queue Number **725065**



Chassis Number **KL1JD7D5XGB743195**
 Engine Number
 Vehicle Class **Car**
 Manufacturer **Chevrolet**
 Model **Trax LT**
 Model Year **2016**
 Color **Grey**
 Mileage **248128 Km**
 Fuel Type **Petrol**
 No. Of Cylinders **4**
 Specification **GCC Specification**

| DEFECT | REMARKS | |
|------------------------------------|--|------------------------|
| 01 Chassis Condition | | الشاشي |
| 01.A Chassis | CHECKED VISIBLE AREA OK | الشاسيه |
| 02 Tires and Rims Condition | | الاطارات |
| 02.A Front Tyre | BOTH SIDE 2020,CRACKED | الاطار الامامي |
| 02.B Rear Tyre | BOTH SIDE 2020,CRACKED | الاطار الخلفي |
| 03 Interior Condition | | الحاله الداخليه |
| 03.A AC Condition | NOT COOLING | المكيف |
| 03.B Roof Ceiling | MINOR CUT | بطانه السقف |
| 04 Suspension System | | ممتص الصدمات |
| 04.A Arms | LOWER ARM BUSHES CRACKED | ازرع |
| 05 Body | | جسم المركبة |
| 05.A Fenders | FRONT BOTH SIDE REPAINTED,PORTION REPAIRED,REFITTED | مدكار |
| 05.B Bumper | MISALIGN,PORTION DAMAGED | دعامية |
| 05.C Rusty | UNDER BODY SUSPENSION PARTS GETTING RUSTY | صدأ |
| 05.D Paint | BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENT,SCRATCHES,PORTION FADED | الصبغ |

| DEFECT | REMARKS | |
|----------------------------------|---------------------------------|--------------------------|
| 05.E Doors | FRONT LEFT SIDE REPAINTED | أبواب |
| 06 Engine Cooling System | | نظام تبريد المحرك |
| 06.A Radiator Condition | COOLANT LEAK | حالة المبرد |
| 07 Transmission Condition | | الجير |
| 07.A Road Test | NOT CHECKED | فحص علي الطريق |
| 07.B Visual Gear Box Condition | JERKING | حالة الجير النظرى |
| 08 Lights | | الاضاءة |
| 08.A Tail Light | RIGHT SIDE PORTION DAMAGED | الانارة |
| 08.B Head Light | RIGHT SIDE LENS PORTION DAMAGED | الاضاءة الرئيسية |
| 09 Engine Condition | | المحرك |
| 09.A Visual Engine Condition | MINOR OIL LEAK ,OVER HEAT | حالة المحرك النظرى |

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.