



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	11 Jan 2022, 18:15:41
Transaction Number	54565124 (CC10006)	Queue Number	312309



Chassis Number	5N1AA0NC3DN607454
Engine Number	
Vehicle Class	Car
Manufacturer	Nissan
Model	Armada
Model Year	2013
Color	White
Mileage	100253 Km
Fuel Type	Petrol
No. Of Cylinders	8
Specification	GCC Specification

DEFECT	REMARKS	
01 Lights		الاضاءة
01.A Fog light	RIGHT SIDE NOT WORKING	كشاف الضباب
01.B Brake Light	RIGHT SIDE COVER CRACKED	نور الفرامل
01.C Head Light	OK	الاضاءة الرئيسية
02 Transmission Condition		الجير
02.A Road Test	NOT CHECK	فحص علي الطريق
02.B Gear Box Mount	BUSH CRACKED	كرسي الجير
03 Wipers and Arms		المساحات
03.A Wiper Arm &Blade	WORN OUT	ازرع المساحات والشفرات
04 Body		جسم المركبة
04.A Fenders	FRONT BOTH SIDE & REAR RIGHT SIDE PORTION REPAIRED, REPAINTED	مدكار
04.B Doors	RIGHT SIDE BOTH REPAINTED	أبواب
04.C Bumper	REPAINTED	دعامية
04.D Roof	PORTION REPAIRED, REPAINTED	السقف
04.E Door Handle &Lock	FRONT BOTH SIDE OUTER COVER MISSING & REAR RIGHT SIDE OUTER HANDLE NOT WORKING	مقابض الأبواب والأقفال

DEFECT	REMARKS	
04.F Bonnet	REPAINTED	غطاء المحرك
04.G Trunk	SHOCK WEAK	صندوق
04.H Paint	PORTION REPAIRED, REPAINTED & DENTS, SCRATCHES ON BODY	الصبغ
05 Interior Condition		الحالة الداخليه
05.A AC Condition	OK & REAR GRAIL PORTION DAMAGED	المكيف
05.B Door Panel	LEFT SIDE BOTH CPORTION CRACKED	لوحة بطانة الباب
05.C Sunroof	NOT WORKING	فتحت سقف
05.D Power Window Switch	FRONT BOTH SIDE NOT WORKING	مفتاح النافذه
05.E Mirror	LEFT SIDE CRACKED	المرايا
06 Engine Condition		المحرك
06.A Mount	BUSHES CRACKED	كرسي
07 Chassis Condition		الشاصي
07.A Chassis	CHASSIS FRAME GETTING RUSTY	الشاسيه
08 Seats Condition		المقاعد
08.A Seat Condition	DRIVER SEAT BACK COVER LOOSE	حالة المقاعد
09 Tires and Rims Condition		الاطارات
09.A Front Tyre	BOTH SIDE 2020	الاطار الامامي
09.B Rear Tyre	BOTH SIDE 2020	الاطار الخلفي
10 Steering Condition		المقود
10.A Steering Boot	LEAKING	ربلة المقود
11 Suspension System		ممتص الصدمات
11.A Arms	FRONT BOTH SIDE LOWER ARMS & REAR CONTROL ARMS BUSHES CRACKED	ازرع

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.