



## TEST CERTIFICATE

Site Number	<b>840-Emirates Auctions</b>	Transaction Date	<b>08 Mar 2023, 16:44:58</b>
Transaction Number	<b>23159521 (CC10009)</b>	Queue Number	<b>685367</b>



Chassis Number	<b>KMHET41CX6A201738</b>
Engine Number	
Vehicle Class	<b>Car</b>
Manufacturer	<b>Hyundai</b>
Model	<b>Sonata</b>
Model Year	<b>2006</b>
Color	<b>--</b>
Mileage	<b>001 Km</b>
Fuel Type	<b>Petrol</b>
No. Of Cylinders	<b>4</b>
Specification	<b>GCC Specification</b>

DEFECT	REMARKS	
<b>01 Body</b>		<b>جسم المركبة</b>
01.A Floor	UNDER FLOOR PARTS CHASSIS SUSPENSION NOT CHECKED	الارضية
01.B Vehicle Color	WHITE	لون المركبة
01.C Other	VISUAL TEST ONLY	اخرى
01.D Bumper	MISALIGN	دعامية
01.E Paint	BODY PAINT NOT CHECKED PORTION RUSTY FADED DUSTY DENT SCRATCHES	الصبغ
<b>02 Interior Condition</b>		<b>الحاله الداخليه</b>
02.A Odometer reading	NOT CHECKED	قراءة عداد المسافات
02.B AC Condition	NOT CHECKED	المكيف
02.C Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
02.D Door Panel	PORTION LOOSE	لوحة بطانة الباب
<b>03 Chassis Condition</b>		<b>الشاسي</b>
03.A Chassis Number	VIN CHECKED ON STICKER	رقم القاعدة
03.B Chassis	CHASSIS NOT CHECKED	الشاسيه

DEFECT	REMARKS	
<b>04 Lights</b>		<b>الاضاءة</b>
04.A Head Light	LENS FADED	الاضاءة الرئيسية
<b>05 Seats Condition</b>		<b>المقاعد</b>
05.A Seat Condition	EXTRA COVER DAMAGED	حالة المقاعد
<b>06 Transmission Condition</b>		<b>الجير</b>
06.A Visual Gear Box Condition	NOT CHECKED	حالة الجير النظرى
<b>07 Engine Condition</b>		<b>المحرك</b>
07.A Visual Engine Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED ,	حالة المحرك النظرى
<b>08 Tires and Rims Condition</b>		<b>الاطارات</b>
08.A Front Tyre	CRACKED DATE NOT CHECKED	الاطار الامامي
08.B Rear Tyre	CRACKED DATE NOT CHECKED	الاطار الخلفي

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.