



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	08 Mar 2023, 12:05:30
Transaction Number	34073238 (CC10010)	Queue Number	685445



Chassis Number	JN8AY2NY4J9350367
Engine Number	
Vehicle Class	Car
Manufacturer	Nissan
Model	Patrol
Model Year	2018
Color	Silver
Mileage	62484 Km
Fuel Type	Petrol
No. Of Cylinders	8
Specification	GCC Specification

DEFECT	REMARKS	
01 Tires and Rims Condition		الاطارات
01.A Front Tyre	BOTH SIDE 2021	الاطار الامامي
01.B Rear Tyre	BOTH SIDE 2021.	الاطار الخلفي
02 Body		جسم المركبة
02.A Paint	BODY PORTION REPAIRED ,REPAINTED .MINOR DENTS SCRATCHES.	الصبغ
02.B Rusty	UNDER BODY ,SUSPENSION PARTS GETTING RUSTY .	صدأ
02.C Bonnet	STAY SHOCK WEAK .	غطاء المحرك
02.D Fuel Tank	COVER DENT .	خزان الوقود
02.E Bumper	MISALIGN.	دعامية
02.F Vehicle Color	GRAY.	لون المركبة
02.G Floor	UNDER FLOOR RUSTPROOFED.	الارضية
02.H Doors	BOTH SIDE DOOR REPAINTED ,FRONT RIGHT SIDE REPAIRED.	أبواب
02.I Fenders	FRONT RIGHT REFITTED.REAR BOTH SIDE QUARTER PANEL REPAINTED.	مدكار
03 Interior Condition		الحالة الداخلية
03.A Other	4X4 SWITCHES NOT WORKING PROPERLY.	اخرى

DEFECT	REMARKS	
03.B Dash Board	GLOVE BOX LOOSE.	لوحة القيادة
03.C AC Condition	OK	المكيف
04 Suspension System		ممتص الصدمات
04.A Arms	LOWER ARM BUSHES CUT .	ازرع
05 Transmission Condition		الجير
05.A Road Test	NOT CHECKED.	فحص علي الطريق
05.B Visual Gear Box Condition	REFITTED OIL LEAK .	حالة الجير النظرى
06 Engine Condition		المحرك
06.A Visual Engine Condition	REFITTED.	حالة المحرك النظرى
07 Wipers and Arms		المساحات
07.A Other	WATER TANK CAP MISSING.	اخرى
08 Brake Condition		الفرامل
08.A Brake Pedal	SPONGY ,ABS LIGHT ON IN CLUSTER.	دواسة الفرامل
09 Chassis Condition		الشاسي
09.A Chassis	COMPLETE CHASSIS FRAME RUSTPROOFED, OK.	الشاسيه
10 Lights		الاضاءة
10.A Warning Light	WARNING LIGHT ON IN DASH BOARD CLUSTER.	ضوء تحذير

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.