



## TEST CERTIFICATE

Site Number	<b>840-Emirates Auctions</b>	Transaction Date	<b>14 Sep 2021, 16:03:31</b>
Transaction Number	<b>48837274 (CC10006)</b>	Queue Number	<b>312309</b>



Chassis Number	<b>JTMHU01J2H5131038</b>
Engine Number	
Vehicle Class	<b>Car</b>
Manufacturer	<b>Toyota</b>
Model	<b>Land Cruiser</b>
Model Year	<b>2017</b>
Color	<b>--</b>
Mileage	<b>326418</b>

DEFECT	REMARKS	
<b>01 Body</b>		<b>جسم المركبة</b>
01.A Fenders	REAR RIGHT SIDE REPAIRED & REPAINTED	مدكار
01.B Paint	PORTION REPAIRED, REPAINTED & DENTS, SCRATCHES ON BODY	الصبغ
01.C Doors	REAR RIGHT SIDE REPAINTED	أبواب
01.D Rusty	UNDER BODY PARTS, CHASSIS FRAME GETTING RUSTY	صدأ
01.E Floor	REAR RIGHT SIDE QUATER PANEL DENT	الارضية
01.F Bumper	MISALIGN	دعامية
<b>02 Chassis Condition</b>		<b>الشاسي</b>
02.A Chassis	CHASSIS FRAME & BODY MOUNT GETTING RUSTY	الشاسيه
<b>03 Engine Condition</b>		<b>المحرك</b>
03.A Other	OK	اخرى
<b>04 Seats Condition</b>		<b>المقاعد</b>
04.A Other	OK	اخرى
<b>05 Wipers and Arms</b>		<b>المساحات</b>
05.A Other	OK	اخرى
<b>06 Tires and Rims Condition</b>		<b>الاطارات</b>
06.A Front Tyre	BOTH SIDE 2020	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2020	الاطار الخلفي

DEFECT	REMARKS	
<b>07 Transmission Condition</b>		<b>الجير</b>
07.A Gear Box	OK	الجير
<b>08 Lights</b>		<b>الاضاءة</b>
08.A Head Light	OK	الاضاءة الرئيسية
08.B Other	OK	اخرى
<b>09 Brake Condition</b>		<b>الفرامل</b>
09.A Caliber Brake	GETTING RUSTY	جهاز الفرامل
<b>10 Suspension System</b>		<b>ممتص الصدمات</b>
10.A Arms	FRONT BOTH SIDE LOWER ARMS & REAR CONTROL ARMS BUSHES CRACKED, RUSTY	ازرع
10.B Shock Absorber	WEAK & RUSTY	ممتص الصدمات
<b>11 Steering Condition</b>		<b>المقود</b>
11.A Other	STABILIZER LINK & CONTROL BAR BUSHES CUT	اخرى
<b>12 Interior Condition</b>		<b>الاجزاء الداخلية</b>
12.A Other	OK	اخرى
12.B Mirror	OK	المرآيا
12.C AC Condition	OK	المكيف

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.