CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2965714
Transaction Date	10 Nov 2026, 12:55:29
Site Name	840 - Emirates Auctions
Transaction Number	77049001 (CC10010) (CC10010)



Vehicle Details

Chassis Number	5N1AA08C47*******
Specification	GCC Specification
Make	Nissan
Model	Armada
Model Year	2007
Color	White
Mileage	N/A Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	REAR IRGHT SIDE QUARTER PANEL REPAINTED PORTION REPAIRED.	مدكار
01.B Paint	BODY PORTION REPAINTED, PORTION REPAIRED DENTS, SCRATCHES , PORTION RUSTY, PORTION FADED	الصبغ
01.C Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY.	صدأ
01.D Floor	UNDER FLOOR PORTION DENT ,MUDDY.,	الارضية
01.E Bumper	MISALIGN,SCRATCHES , LOOSE ,PORTION DAMAGED.	دعامية
01.F Windshield	FRONT SPOT CRACKED.	زجاج
01.G Trunk	NOT OPEN	صندوق
01.H Sign of front accident	FRONT BUMPER FRAME , RADIATOR SUPPORT BULK HEAD,FENDER FRAME CROSS MEMBER REPAIRED.	وجود مؤشر لحادث في المقدمة
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS FRAME RUSTY PORTION DENT ,PORTION MUDDY .	الشاسيه
02.B Chassis Number	VIN CHECKED ONLY STICKER.	رقم القاعدة
03 Engine Condition		المحرك
03.A Mount	BUSHES CRACKED.	كرسي
03.B Engine Visual Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED ,REFITTED OIL LEAK,PARTS RUSTY	الحالة النظريه للمحرك
04 Seats Condition		المقاعد

Condition	Remarks	الحالة
04.A Seat Condition	LOOSE PORTION CUT ,BACK COVER LOOSE	حالة المقاعد
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	NOT CHECKED ,REFITTED,OIL LEAK ,COMPONENT PARTS RUSTY .	الحالة النظريه للجير
05.B Road Test	NOT CHECKED .	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2024 CRACKED .	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2024 CRACKED .	الاطار الخلفي
06.C Rims Condition	MINOR SCRATCHES .	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	LENS FADED, ALL LIGHTS NOT CHECK	الاضاءة الرئيسية
07.B Tail Light	PORTION CRACKED .	الضوء الخلفي
08 Brake Condition		الفرامل
08.A Disc&Drum	RUSTY	دسك وطنابير الفرامل
09 Suspension System		ممتص الصدمات
09.A Shock Absorber	LEAK .	ممتص الصدمات
09.B Stabilizer Bar And Link Rod	BUSHES CRACKED.	عمود التوازن و مثبت عمود التوازن
10 Steering Condition		المقود
10.A Steering Boot	CUT .	ربلة المقود
10.B Steering Box	OIL LEAK .	جهاز المقود
10.C Axle	BOOT CRACKED.	اكسلات
11 Interior Condition		الحاله الداخليه
11.A Other	INTERIOR PARTS GETTING RUSTY ,SIGN OF FLOODED.	اخري
11.B Mirror	FADED ,PORTION LOOSE.	المرايا
11.C AC Condition	NOT CHECKED .	المكيف
11.D Dash Board	PORTION LOOSE	لوحة القياده
11.E Odometer reading	NOT CHECKED .	قراءة عداد المسافات
11.F Steering Wheel and control buttons	WORN OUT .	عجلة القيادة وازرار التحكم
11.G Gear Shifting Lever	KNOB WORN OUT .	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص

only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر **wecare@carscheck.ae**