CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2966818
Transaction Date	11 Nov 2026, 11:15:38
Site Name	840 - Emirates Auctions
Transaction Number	36930456 (CC10010) (CC10010)



Vehicle Details

Chassis Number	MDHBN7AD1L*******
Specification	GCC Specification
Make	Nissan
Model	Sunny
Model Year	2020
Color	White
Mileage	222438 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		**جسم المركبة**
01.A Fenders	REAR BOTH SIDE QUARTER PANEL REPAIRED REPAINTED.	مدكار
01.B Paint	BODY PORTION REPAINTED, PORTION REPAIRED DENTS, SCRATCHES , PORTION RUSTY, PORTION FADED	الصبغ
01.C Doors	PORTION REPAINTED.	أبواب
01.D Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY.	صدأ
01.E Floor	UNDER FLOOR PORTION DENT ,MUDDY.,	الارضية
01.F Bumper	MISALIGN,SCRATCHES , PORTION LOOSE ,PORTION DAMAGED.	دعامية
01.G Trunk	REPAIRED REPAINTED.	صندوق
01.H Sign of back accident	BACK PANEL ,QUARTER PANEL COMPARTMENT FLOOR REPAIRED.	وجود مؤشر لحادث في الخلف
02 Chassis Condition		**الشاصي**
02.A Chassis	REAR RIGHT SIDE CHASSIS EXTENSION END KINK DENT , ,FRONT CHASSIS COVERED ,CHECKED ONLY VISIBLE AREA .	الشاسيه
03 Engine Condition		**المحرك**
03.A Smoke	MINOR WHITE.	دخان
03.B Engine Visual Condition	OIL LEAK ,PARTS RUSTY GET SHAKING , COMPONENT PARTS REFITTED.	الحالة النظريه للمحرك
04 Seats Condition		**المقاعد**
04.A Seat Condition	DIRTY ,PORTION LOOSE ,PORTION CUT .	حالة المقاعد

Condition	Remarks	الحالة
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	OIL LEAK , PARTS REFITTED ,GET JERKING.	الحالة النظريه للجير
05.B Gear Box Mount	BUSHES CRACKED .	كرسي الجير
05.C Road Test	NOT CHECKED .	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2024 DRY CRACKED .	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2024 DRY CRACKED .	الاطار الخلفي
07 Lights		الاضاءة
07.A Head Light	LENS FADED.	الاضاءة الرئيسية
07.B Warning Light	EXTRA WARNING LIGHT ON IN CLUSTER	ضوء تحذير
08 Brake Condition		الفرامل
08.A Brake Pedal	SPONGY.	دواسة الفرامل
08.B Disc&Drum	RUSTY.	دسك وطنابير الفرامل
09 Suspension System		ممتص الصدمات
09.A Shock Absorber	LEAK .	ممتص الصدمات
09.B Arms	BUSHES CRACKED .	ازرع
10 Interior Condition		الحاله الداخليه
10.A Other	INTERIOR PARTS GETTING RUSTY ,SIGN OF FLOODED.	اخري
10.B AC Condition	NOT COOLING.	المكيف
10.C Door Panel	WORN OUT PORTION LOOSE	لوحة بطانة الباب
10.D Steering Wheel and control buttons	WORN OUT .	عجلة القيادة وازرار التحكم
10.E Gear Shifting Lever	KNOB WORN OUT .,	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae