



TEST CERTIFICATE

Site Number **840-Emirates Auctions** Transaction Date **12 Mar 2025, 09:13:38**
 Transaction Number **42037954 (CC10018) (CC10019)** Queue Number **1382546**



Chassis Number **1GNFK16Z44J147414**
 Engine Number
 Vehicle Class **Car**
 Manufacturer **GMC**
 Model **Suburban**
 Model Year **2004**
 Color **White**
 Mileage **N/A NA**
 Fuel Type **Petrol**
 No. Of Cylinders **8**
 Specification **Imported**

DEFECT	REMARKS	
01 Body		جسم المركبة
01.A Paint	BODY PORTION REPAINTED ,PORTION REPAIRED ,MINOR DENTS SCRATCHES ,PORTION RUSTY PORTION FADED.	الصبغ
01.B Floor	UNDER BODY PARTS, SUSPENSION, FLOOR, CHASSIS NOT CHECK	الارضية
01.C Bumper	MISALIGN ,PORTION DAMAGED	دعامية
01.D Windshield	FRONT CRACKED	زجاج
01.E Roof	RUSTY, HOLE	السقف
01.F Other	VISUAL TEST ONLY, SIGN OF WATER FLOODED	اخرى
02 Chassis Condition		الشاسي
02.A Chassis	NOT CHECK	الشاسيه
03 Engine Condition		المحرك
03.A Engine Visual Condition	NOT START , ALL SYSTEM NOT CHECK	الحالة النظرية للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	COVER DAMAGED ,REAR MISSING	حالة المقاعد
05 Transmission Condition		الجير

DEFECT	REMARKS	
05.A Gear Box Visual Condition	NOT CHECK	الحالة النظرية للجير
05.B Road Test	NOT CHECK	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	CRACKED DAMAGED	الاطار الامامي
06.B Rear Tyre	CRACKED DAMAGED	الاطار الخلفي
07 Lights		الاضاءة
07.A Head Light	LEFT SIDE COVER PORTION DAMAGED & LENS FADED , ALL LIGHTS NOT CHECK	الاضاءة الرئيسية
07.B Tail Light	LEFT SIDE COVER PORTION DAMAGED	الانارة
08 Interior Condition		الحالة الداخلية
08.A Other	INTERIOR CONDITION DIRTY	اخرى
08.B AC Condition	NOT CHECKED	المكيف
08.C Power Window Switch And Glass	AUTO SWITCH LOOSE	مفتاح النافذه و الزجاج
08.D Audio	MISSING	صوتيات
08.E Dash Board	PORTION DAMAGED	لوحة القيادة
08.F Roof Ceiling	PORTION DAMAGED LOOSE	بطانة السقف
08.G Odometer reading	NOT CHECKED	قراءة عداد المسافات
08.H Door Panel	PORTION DAMAGED LOOSE	لوحة بطانة الباب
08.I Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
09 Battery Condition		حالة البطارية
09.A Battery Condition	MISSING	حالة البطارية

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.
- For complaints and inquiries reach out to us on wecare@carscheck.ae



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.
- للاشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae