



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	12 Jan 2022, 17:52:42
Transaction Number	67299116 (CC10006)	Queue Number	312309



Chassis Number	MHKMC13F5FK018883
Engine Number	
Vehicle Class	Car
Manufacturer	Toyota
Model	Avanza
Model Year	2015
Color	Silver
Mileage	244438 Km
Fuel Type	Petrol
No. Of Cylinders	4
Specification	GCC Specification

DEFECT	REMARKS	
01 Lights		الاضاءة
01.A Head Light	MINOR FADED ,LOOSE & PARKING LIGHTS NOT WORKING	الاضاءة الرئيسية
01.B Fog light	LEFT SIDE NOT WORKING	كشاف الضباب
02 Interior Condition		الحالة الداخليه
02.A AC Condition	OK & MIDDLE RIGHT SIDE MINOR DAMAGED	المكيف
02.B Mirror	ADJUSTMENT NOT WORKING	المرآيا
02.C Door Panel	LOOSE	لوحة بطانة الباب
03 Body		جسم المركبة
03.A Paint	BODY PORTION REPAINTED,PORTION REPAIRED, MINOR DENT,SCRATCHES	الصبغ
03.B Fenders	REAR BOTH SIDE REPAINTED & LEFT SIDE PORTION REPAIRED	مدكار
03.C Bonnet	REPAINTED,PORTION REPAIRED	غطاء المحرك
03.D Bumper	REPAINTED,MISALIGN	دعامة
04 Tires and Rims Condition		الاطارات
04.A Rear Tyre	BOTH SIDE 2019	الاطار الخلفي
04.B Front Tyre	BOTH SIDE 2019	الاطار الامامي

DEFECT	REMARKS	
04.C Rims Condition	RIMS HAVE MINOR SCRATCHES	حالة الجنوط
05 Chassis Condition		الشاسي
05.A Chassis	OK	الشاسيه
06 Engine Condition		المحرك
06.A Engine Condition	MINOR OIL LEAK	حالة المحرك
07 Transmission Condition		الجير
07.A Gear Box	OK	الجير
07.B Road Test	NOT CHECK	فحص علي الطريق
08 Wipers and Arms		المساحات
08.A Wiper Arm &Blade	WORN OUT	ازرع المساحات والشفرات
09 Seats Condition		المقاعد
09.A Seat Condition	REAR SEATS DAMAGED	حالة المقاعد
09.B Seat Belt	OK	حزام الأمان
10 Battery Condition		حالة البطارية
10.A Battery Condition	NOT WORKING	حالة البطارية
11 Suspension System		ممتص الصدمات
11.A Shock Absorber	REAR RIGHT SIDE MINOR OIL LEAK	ممتص الصدمات

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.