CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2958625
Transaction Date	09 Nov 2026, 13:03:10
Site Name	840 - Emirates Auctions
Transaction Number	89557927 (CC10009) (CC10011)



Vehicle Details

Chassis Number	1C4RJFDJ4D*******
Specification	GCC Specification
Make	Jeep
Model	Grand Cherokee
Model Year	2013
Color	Black
Mileage	254634 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	8

Condition	Remarks	الحالة
01 Body		**جسم المركبة**
01.A Fenders	FRONT BOTH SIDE REPAIRED REPAINTED REFITTED	مدكار
01.B Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENTS SCRATCHES,PORTION FADED RUSTY	الصبغ
01.C Doors	FRONT LEFT SIDE REPAINTED	أبواب
01.D Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.E Floor	FLOOR MUDDY PORTION DENT	الارضية
01.F Bumper	MISALIGN,GRILL PORTION CRACKED	دعامية
01.G Bonnet	REPAINTED PORTION REPAIRED REFITTED,SHOCK WEAK	غطاء المحرك
01.H Sign of front accident	FRONT BUMPER FRAME BULK HEAD FENDER FRAMERADIATOR SUPPORT REPAIRED	وجود مؤشر لحادث في المقدمة
02 Chassis Condition		**الشاصي**
02.A Chassis	FRONT LEFT SIDE CHASSIS REPAITRED , RIGHT SIDE PORTION DENT , MUDDY	الشاسيه
03 Engine Condition		**المحرك**
03.A Engine Visual Condition	OIL LEAK REFITTED, ENGINE KOCKING ABNORMAL NOISY SHAKING	الحالة النظريه للمحرك
04 Seats Condition		**المقاعد**
04.A Seat Condition	COVER PORTION CRACK WORN OUT	حالة المقاعد
05 Transmission Condition		**الجير**

Condition	Remarks	الحالة
05.A Gear Box Visual Condition	MINOR OIL LEAK REFITTED GETTING RUSTY JERKING	الحالة النظريه للجير
05.B Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2024 CRACK	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2023 CRACKED	الاطار الخلفي
06.C Rims Condition	MINOR DENTS SCRATCHES	حالة الجنوط
07 Lights		الاضاءة
07.A Tail Light	PORTION CRACK	الضوء الخلفي
07.B Brake Light	LEFT SIDE NOT WORKING	نور الفرامل
07.C Revers Light	NOT WORKING	نور الرجوع للخلف
08 Suspension System		ممتص الصدمات
08.A Arms	LOWER ARM BUSHES CUT, ARM BEND	ازرع
08.B Other	SUSPENSION REFITTED	اخري
09 Steering Condition		المقود
09.A Steering Oil	OIL LEAK	زيت المقود
09.B Steering Boot	BOOT CUT	ربلة المقود
09.C Tie Rod End	BOOT CUT	مؤخرة الرودات
10 Interior Condition		الحاله الداخليه
10.A Other	CENTER CONSOLE BOX COVER WORN OUT,CUP HOLDER PANEL PORTION WORN OUT CRACKED, INNERPARTS GETTING RUSTY, SIGN OF FLOODED	اخري
10.B Mirror	RIGHT SIDE LOOSE AUTO FOLDING NOT WORKING	المرايا
10.C AC Condition	OK,FRONT RIGHT SIDE GRILL LOOSE PORTION CRACK	المكيف
10.D Audio	SCREEN PORTION FADED,ANTENNA DAMAGED	صوتيات
10.E Dash Board	PORTION WORN OUT,LEATHER REFITTED PORTION LOOSE	لوحة القياده
10.F Door Panel	PORTION WORN OUT LOOSE	لوحة بطانة الباب
10.G Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
10.H Sunroof	CURTAIN LOOSE	فتحت سقف
10.I Gear Shifting Lever	KNOB WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة،
كما لا تضمن بموجب هذه الشهادة صلاحية المركبة
.للتسجيل من عدمه

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae