

Queue Number 2837275

Transaction Date 08 Oct 2026, 12:03:48

Site Name
840 - Emirates AuctionsTransaction Number
80272992 (CC10021) (CC10019)

Vehicle Details

Chassis Number	3N1AB7AP5D*****
Specification	Imported
Make	Nissan
Model	Sentra
Model Year	2013
Color	Red
Mileage	N/A NA
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Paint	BODY PORTION REPAINTED, PORTION REPAIRED, MINOR DENTS & SCRATCHES, PORTION RUSTY, PORTION FADED	الصبغ
01.B Rusty	UNDER BODY PARTS ,SUSPENSION GETTING RUSTY	صدأ
01.C Floor	UNDER FLOOR PORTION DENTS, MUDDY,NEED TO REMOVE BOTH SIDE FENDER COVER FOR PROPER INSPECTION	الارضية
01.D Bumper	MISALIGN PORTION DAMAGED	دعامية
01.E Sign of front accident	BUMPER FRAME,FENDER FRAME,RADIATOR FRAME SUPPORT REPAIRED	وجود مؤشر لحادث في المقدمة

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS COVERED,MUDDY,PORTION DENT	الشاسيه
--------------	------------------------------------	---------

03 Engine Condition

المحرك

03.A Engine Visual Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED REFITTED OIL LEAK . PARTS RUSTY	الحالة النظرية للمحرك
------------------------------	--	-----------------------

04 Transmission Condition

الجير

04.A Gear Box Visual Condition	NOT CHECKED REFITTED OIL LEAK PARTS RUSTY	الحالة النظرية للجير
04.B Road Test	NOT CHECKED	فحص علي الطريق

05 Tires and Rims Condition

الاطارات

05.A Front Tyre	BOTH SIDE 2024 WORN OUT	الاطار الامامي
-----------------	-------------------------	----------------

Condition	Remarks	الحالة
05.B Rear Tyre	BOTH SIDE 2024 WORN OUT	الاطار الخلفي
06 Lights		الاضاءة
06.A Head Light	LENS FADED, ALL LIGHTS NOT CHECKED	الاضاءة الرئيسية
06.B Tail Light	PORTION DAMAGED	الضوء الخلفي
07 Brake Condition		الفرامل
07.A Disc&Drum	RUSTY	دسك و طنابير الفرامل
08 Suspension System		ممتص الصدمات
08.A Arms	BUSHES CRACK	ازرع
08.B Ball Joint	BOOT CUT	مفصل كروي
08.C Stabilizer Bar And Link Rod	BOOT CUT	عمود التوازن و مثبت عمود التوازن
09 Interior Condition		الحالة الداخلية
09.A Other	INTERIOR PARTS RUSTY, SIGN OF WATER FLOODED	اخرى
09.B Mirror	CENTER MIRROR PORTION FADED	المرآيا
09.C AC Condition	NOT CHECKED	المكيف
09.D Dash Board	GETTING FADED PORTION WORN OUT	لوحة القيادة
09.E Odometer reading	NOT CHECKED	قراءة عداد المسافات
09.F Door Panel	PORTION WORN OUT	لوحة بطانة الباب
09.G Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
09.H Gear Shifting Lever	KNOB WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on wecare@carscheck.ae

لشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae