

Queue Number 1848189

Transaction Date 15 Oct 2025, 17:09:32

Site Number
840 - Emirates AuctionsTransaction Number
53432270 (CC10013) (CC10012)

Vehicle Details

Chassis Number	SCA682D02D*****
Specification	GCC Specification
Make	Rolls Royce
Model	Phantom
Model Year	2013
Color	White
Mileage	82406 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	12

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Paint	BODY TOTALLY THICK DUST , PAINT CANNOT CHECK PROPERLY	الصبغ
01.B Rusty	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY	صدأ
01.C Floor	UNDER FLOOR COMPLETELY COVERED CHECK VISIBLE AREA ONLY	الارضية
01.D Bumper	MISALIGN , SCRATCHES	دعامية
01.E Windshield	WINDSHIELD NO VISIBLE TO CHECK	زجاج
01.F Pillars	INNER OUTER PANEL COVER WORN OUT	القوائم
01.G Other	LOGO GETTING RUSTY	اخرى
01.H Vehicle Color	WHITE / SILVER	لون المركبة

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS COMPLETELY COVERED CHECK VISIBLE AREA ONLY / OK	الشاسيه
02.B Chassis Number	DOOR POST STICKER PORTION DAMAGED	رقم القاعدة

03 Engine Condition

المحرك

03.A Other	COMPARTMENT ELECTRIC WIRE UNSAFE	اخرى
03.B Engine Visual Condition	OIL LEAK , REFITTED , SIGN OF OVERHEAT	الحالة النظرية للمحرك

04 Transmission Condition

الجير

04.A Gear Box Visual Condition	OIL LEAK , REFITTED	الحالة النظرية للجير
--------------------------------	---------------------	----------------------

Condition	Remarks	الحالة
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	BOTH SIDE 2020 EXPIRED CRACK	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2020 EXPIRED CRACK	الاطار الخلفي
05.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
06 Brake Condition		الفرامل
06.A Disc&Drum	GETTING RUSTY	دسك و طنابير الفرامل
07 Suspension System		ممتص الصدمات
07.A Other	SUSPENSION PARTS REFITTED	اخرى
08 Interior Condition		الحالة الداخلية
08.A Other	INTERIOR PARTS DIRTY MUDDY	اخرى
08.B AC Condition	NO COOLING	المكيف
08.C Power Window Switch And Glass	REAR LEFT SIDE GLASS MISSING	مفتاح النافذه و الزجاج
08.D Steering Wheel and control buttons	GETTING WORN OUT	عجلة القيادة وازرار التحكم
08.E Sunroof	CONVERTIBLE NOT WORKING , WORN OUT	فتحت سقف
09 Engine Cooling System		نظام تبريد المحرك
09.A Coolant tank	WATER BOTTLE LEAK	خزان التبريد

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on wecare@carscheck.ae

للسكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae