CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2899652
Transaction Date	29 Oct 2026, 13:22:27
Site Name	840 - Emirates Auctions
Transaction Number	31820264 (CC10006) (CC10006)



Vehicle Details

Chassis Number	WBAHN81008*******
Specification	GCC Specification
Make	BMW
Model	750LI
Model Year	0
Color	Black
Mileage	N/A Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	8

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	REAR BOTH SIDE REPAINTED PORTION REPAIRED	مدكار
01.B Paint	BODY PORTION REPAINTED , PORTION REPAIRED, DENTS, SCRATCHES	الصبغ
01.C Doors	REAR BOTH SIDE REPAINTED PORTION REPAIRED	أبواب
01.D Rusty	UNDER BODY PARTS ,SUSPENSION GETTING RUSTY	صدأ
01.E Floor	UNDER BODY FULLY COVERED CHECKED VISIBLE AREA ONLY	الارضية
01.F Bumper	MISALIGN , PORTION DAMAGE , TOW HOOK COVER MISSING	دعامية
01.G Bonnet	STAY SHOCK WEAK NOT WORKING	غطاء المحرك
01.H Door Handle &Lock	REAR LEFT SIDE OUTER HANDLE LOCK DAMAGE	مقابض الأبواب والأقفال
01.I Vehicle Year Model	2008	سنة صنع المركبة
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS COVERED OILY , CHECK VISIBLE AREA ONLY / OK	الشاسيه
03 Engine Condition		المحرك
03.A Engine Visual Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED REFITTED OIL LEAK . PARTS RUSTY	الحالة النظريه للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	DAMAGE	حالة المقاعد
05 Transmission Condition		الجير

Condition	Remarks	الحالة
05.A Gear Box Visual Condition	NOT CHECKED REFITTED OIL LEAK PARTS RUSTY	الحالة النظريه للجير
05.B Road Test	NOT CHECK	فحص علي الطريق
06 Tires and Rims Condition		**الاطارات**
06.A Front Tyre	BOTH SIDE 2024	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2024	الاطار الخلفي
06.C Rims Condition	DENT SCRATCHES	حالة الجنوط
07 Lights		**الاضاءة**
07.A Head Light	LENS FADED, ALL LIGHTS NOT CHECKED	الاضاءة الرئيسية
07.B Tail Light	CRACK	الضوء الخلفي
07.C Fog light	LENS FADED	كشاف الضباب
08 Brake Condition		**الفرامل**
08.A Disc&Drum	RUSTY	دسك وطنابير الفرامل
09 Suspension System		**ممتص الصدمات**
09.A Shock Absorber	BODY LEVEL LOW	ممتص الصدمات
09.B Arms	BUSHES CRACK	ازرع
09.C Stabilizer Bar And Link Rod	BOOT CUT	عمود التوازن و مثبت عمود التوازن
10 Interior Condition		**الحاله الداخليه**
10.A Other	CENTER CONSOLE BOX COVER WORN OUT , INETRIOR PARTS GETTING RUSTY , SIGN OF FLOODED	اخري
10.B AC Condition	NOT CHECK	المكيف
10.C FLoor Matting	DIRTY	فرش الأرضيه
10.D Dash Board	PORTION WORN OUT	لوحة القياده
10.E Roof Ceiling	PORTION WORN OUT	بطانه السقف
10.F Odometer reading	CLUSTER DISPLAY PANEL MELTED	قراءة عداد المسافات
10.G Door Panel	PORTION WORN OUT	لوحة بطانة الباب
10.H Steering Wheel and control buttons	EXTRA COVER	عجلة القيادة وازرار التحكم
10.I Gear Shifting Lever	PORTION WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة،
كما لا تضمن بموجب هذه الشهادة صلاحية المركبة
.للتسجيل من عدمه

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae