



## TEST CERTIFICATE

Site Number **840-Emirates Auctions** Transaction Date **17 May 2022, 12:39:17**  
 Transaction Number **63017353 (CC10008)** Queue Number **312309**



Chassis Number **KMHJM81D69U961695**  
 Engine Number  
 Vehicle Class **Car**  
 Manufacturer **Hyundai**  
 Model **Tucson**  
 Model Year **2009**  
 Color **White**  
 Mileage **191826 Km**  
 Fuel Type **Petrol**  
 No. Of Cylinders **6**  
 Specification **GCC Specification**

DEFECT	REMARKS	
<b>01 Interior Condition</b>		<b>الحاله الداخليه</b>
01.A AC Condition	OK	المكيف
01.B Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
01.C Roof Light	FRONT BUTTON DAMAGED & REAR DAMAGED & CONSOLE BOX MISSING	أنارة السقف
<b>02 Body</b>		<b>جسم المركبة</b>
02.A Paint	BODY PORTION REPAIRED, REPAINTED, MINOR DENT, SCRATCHES	الصبغ
02.B Sign of back accident		وجود مؤشر لحادث في الخلف
02.C Trunk	PORTION REPAIRED, REPAINTED	صندوق
02.D Other	REAR BACK PANEL REPAIRED	اخرى
02.E Doors	FRONT RIGHT SIDE DOOR SKIRT LOOSE	أبواب
<b>03 Steering Condition</b>		<b>المقود</b>
03.A Steering Oil	MINOR OIL LEAK	زيت المقود
<b>04 Tires and Rims Condition</b>		<b>الاطارات</b>
04.A Front Tyre	BOTH SIDE 2021	الاطار الامامي

DEFECT	REMARKS	
04.B Rear Tyre	BOTH SIDE 2021	الاطار الخلفي
<b>05 Transmission Condition</b>		<b>الجير</b>
05.A Road Test	NOT CHECK	فحص علي الطريق
<b>06 Chassis Condition</b>		<b>الشاصي</b>
06.A Chassis	OK	الشاسيه
<b>07 Suspension System</b>		<b>ممتص الصدمات</b>
07.A Arms	FRONT LOWER ARM BUSHES WORN OUT	ازرع
07.B Other	STABLIZER LINK BOOT CUT	اخرى
<b>08 Engine Condition</b>		<b>المحرك</b>
08.A Visual Engine Condition	MINOR OIL LEAK	حالة المحرك النظري

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.