CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2877836
Transaction Date	19 Oct 2026, 17:42:51
Site Name	840 - Emirates Auctions
Transaction Number	24617120 (CC10006) (CC10006)



Vehicle Details

Chassis Number	JN1CC13C19*******
Specification	GCC Specification
Make	Nissan
Model	Tiida
Model Year	2009
Color	Grey
Mileage	N/A Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Paint	BODY PORTION REPAINTED, PORTION REPAIRED, DENTS, SCRATCHES, PORTION FADED, PORTION RUSTY	الصبغ
01.B Rusty	UNDER BODY PARTS ,SUSPENSION GETTING RUSTY	صدأ
01.C Floor	UNDER FLOORING , RUNNING BOARD , WHEEL ARCH REAPIRED	الارضية
01.D Bumper	MISALIGN, PORTION DAMAGED	دعامية
01.E Sign of front accident	FRONT BUMPER FRAME, BULKHEAD, RADIATOR SUPPORT, FENDER FRAME REPAIRED	وجود مؤشر لحادث في المقدمة
01.F Sign of back accident	BACK PANEL, QUATER PANEL, COMPARTMENT REPAIRED	وجود مؤشر لحادث في الخلف
02 Chassis Condition		الشاصي
02.A Chassis	FRONT BOTH SIDE CHASSIS & REARBOTH SIDE CHASSIS END REPAIRED, FRONT RIGHT SIDE BEND	الشاسيه
03 Engine Condition		المحرك
03.A Engine Visual Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED REFITTED OIL LEAK . PARTS RUSTY	الحالة النظريه للمحرك
04 Transmission Condition		الجير
04.A Gear Box Visual Condition	NOT CHECKED REFITTED OIL LEAK PARTS RUSTY	الحالة النظريه للجير
04.B Road Test	NOT CHECK	فحص علي الطريق
05 Tires and Rims Condition		الاطارات

Condition	Remarks	الحالة
05.A Front Tyre	BOTH SIDE CRACK	الاطار الامامي
05.B Rear Tyre	BOTH SIDE CRACK	الاطار الخلفي
05.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
06 Lights		الاضاءة
06.A Head Light	LENS FADED, ALL LIGHTS NOT CHECKED	الاضاءة الرئيسية
07 Suspension System		ممتص الصدمات
07.A Arms	BUSHES CRACK	ازرع
07.B Stabilizer Bar And Link Rod	BOOT CUT	عمود التوازن و مثبت عمود التوازن
08 Interior Condition		الحاله الداخليه
08.A Other	CENTER CONSOLE BOX COVER WORN OUT , INETRIOR PARTS GETTING RUSTY , SIGN OF FLOODED	اخري
08.B AC Condition	NOT CHECK	المكيف
08.C Dash Board	PORTION WORN OUT	لوحة القياده
08.D Roof Ceiling	PORTION WORN OUT	بطانه السقف
08.E Odometer reading	NOT CHECK	قراءة عداد المسافات
08.F Door Panel	PORTION WORN OUT	لوحة بطانة الباب
08.G Steering Wheel and control buttons	PORTION WORN OUT	عجلة القيادة وازرار التحكم
08.H Gear Shifting Lever	PORTION WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae