

Queue Number

2899776

Transaction Date

23 Oct 2026, 14:40:09

Site Name

840 - Emirates Auctions

Transaction Number

45954770 (CC10010) (CC10010)



Vehicle Details

Chassis Number	2GKAL8EK3D*****
Specification	GCC Specification
Make	GMC
Model	Terrain
Model Year	2013
Color	Black
Mileage	212150 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	RIGHT SIDE FRONT & REAR REPAINTED PORTION REPAIRED.	مدكار
01.B Paint	BODY PORTION REPAINTED, PORTION REPAIRED DENTS, SCRATCHES , PORTION RUSTY, PORTION FADED	الصبغ
01.C Doors	RIGHT SIDE BOTH DOORS REPAINTED PORTION REPAIRED.	أبواب
01.D Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY.	صدأ
01.E Floor	UNDER FLOOR PORTION DENT ,MUDDY.,	الارضية
01.F Bumper	BUMPER MISALIGN ,SCRATCHES ,PORTION DAMAGED.	دعامية
01.G Sign of side accident	REAR RIGHT SIDE QUARTER PANEL REPAIRED DENT .	وجود مؤشر لحادث في الجانب

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS COMPLETE COVERED ,OILY MUDDY NOT VISIBLE PROPERLY,CHECKED ONLY VISIBLE AREA /OK.	الشاسيه
--------------	--	---------

03 Engine Condition

المحرك

03.A Engine Visual Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED ,REFITTED OIL LEAK,PARTS RUSTY	الحالة النظرية للمحرك
------------------------------	---	-----------------------

04 Transmission Condition

الجير

04.A Gear Box Visual Condition	NOT CHECKED ,REFITTED,OIL LEAK ,COMPONENT PARTS RUSTY .	الحالة النظرية للجير
04.B Road Test	NOT CHECKED .	فحص علي الطريق

Condition	Remarks	الحالة
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	BOTH SIDE 2021 CRACKED.EXPIRED CRACKED.	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2021 CRACKED.EXPIRED CRACKED.	الاطار الخلفي
05.C Rims Condition	DENTS SCRATCHES.	حالة الجنوط
06 Lights		الاضاءة
06.A Head Light	LENS FADED, ALL LIGHTS NOT CHECK	الاضاءة الرئيسية
07 Brake Condition		الفرامل
07.A Disc&Drum	PARTS RUSTY	دسك و طناير الفرامل
08 Suspension System		ممتص الصدمات
08.A Shock Absorber	LEAK .	ممتص الصدمات
08.B Arms	BUSHES CRACKED	ازرع
09 Steering Condition		المقود
09.A Steering Boot	CUT .	ربلة المقود
09.B Steering Box	OIL LEAK .	جهاز المقود
10 Interior Condition		الحالة الداخلية
10.A Other	INTERIOR PARTS GETTING RUSTY ,SIGN OF FLOODED	اخرى
10.B AC Condition	NOT CHECKED.	المكيف
10.C Door Panel	WORN OUT PORTION LOOSE	لوحة بطانة الباب
10.D Steering Wheel and control buttons	WORN OUT .	عجلة القيادة وازرار التحكم
10.E Gear Shifting Lever	KNOB WORN OUT .	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on wecare@carscheck.ae

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae