



## TEST CERTIFICATE

Site Number	<b>840-Emirates Auctions</b>	Transaction Date	<b>22 Feb 2023, 14:36:57</b>
Transaction Number	<b>88809282 (CC10008)</b>	Queue Number	<b>677891</b>



Chassis Number	<b>SCBBA63Y1CC016224</b>
Engine Number	
Vehicle Class	<b>Car</b>
Manufacturer	<b>Bentley</b>
Model	<b>-</b>
Model Year	<b>2012</b>
Color	<b>Beige</b>
Mileage	<b>165979 Km</b>
Fuel Type	<b>Petrol</b>
No. Of Cylinders	<b>8</b>
Specification	<b>GCC Specification</b>

DEFECT	REMARKS	
<b>01 Chassis Condition</b>		<b>الشاسي</b>
01.A Chassis	CHASSIS FULLY COVERED,VISIBLE AREA CHECKED ONLY /OK	الشاسيه
<b>02 Body</b>		<b>جسم المركبة</b>
02.A Paint	BODY PORTION REPAIRED,REPAINTED	الصبغ
02.B Sign of side accident		وجود مؤشر لحادث في الجانب
02.C Pillars	RIGHT SIDE C/PILLAR REPAIRED	القوائم
02.D Floor	UNDER BODY FULLY COVERED& VISIBLE AREA CHECKED ONLY	الارضيه
02.E Fenders	REFITTED	مدكار
02.F Sign of front accident		وجود مؤشر لحادث في المقدمة
02.G Trunk	AUTO OPENING NOT WORKING PROPERLY	صندوق
02.H Vehicle Model	MULSANNE	طراز المركبة
02.I Bonnet	REFITTED	غطاء المحرك
02.J Bumper	FRONT ASSEMBLY REFITTED	دعامية
<b>03 Tires and Rims Condition</b>		<b>الاطارات</b>
03.A Rims Condition	RIMS HAVE MINOR DENT ,SCRATCHES	حالة الجنوط

DEFECT	REMARKS	
03.B Front Tyre	BOTH SIDE 2021	الاطار الامامي
03.C Rear Tyre	BOTH SIDE 2021	الاطار الخلفي
<b>04 Interior Condition</b>		<b>الحاله الداخليه</b>
04.A Power Window Switch	REAR BOTH SIDE NOT WORKING	مفتاح النافذه
04.B AC Condition	OK	المكيف
04.C Other	REAR WINDSHIELD CURTAIN NOT WORKING	اخرى
04.D Sun Visor	BOTH SIDE BRACKET BROKEN	حاجب الشمس
<b>05 Lights</b>		<b>الاضاءة</b>
05.A Warning Light	WARNING LIGHT ON IN DISPLAY	ضوء تحذير
<b>06 Transmission Condition</b>		<b>الجير</b>
06.A Road Test	NOT CHECKED	فحص علي الطريق
06.B Visual Gear Box Condition	OK	حالة الجير النظرى
<b>07 Engine Condition</b>		<b>المحرك</b>
07.A Visual Engine Condition	OK	حالة المحرك النظرى
<b>08 Suspension System</b>		<b>ممتص الصدمات</b>
08.A Suspension Subframe	FRONT SUB FRAME REFITTED	
08.B Arms	LOWER ARM BUSHES CRACKED	ازرع

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.