

# **TEST CERTIFICATE**

Site Number
Transaction Number

840-Emirates Auctions 27283726 (CC10006) Transaction Date

28 Jun 2022, 16:00:33

Queue Number

312309



1FA6P8CF9L5168883

Engine Number

Vehicle Class Car

Manufacturer Ford

Model Mustang

Model Year 2020

Color Blue

Mileage 2924 Miles

Fuel Type Petrol

No. Of Cylinders

Specification USA Imported



**DEFECT** REMARKS

| 01 Body                     |   | جسم المركبة                |
|-----------------------------|---|----------------------------|
| 01.A Pillars                | RIGHT SIDE DOOR PILLAR ,ROCKER PANEL REPAIRED                         | القوائم                    |
| 01.B Paint                  | BODY REPAINTED, PORTION REPAIRED, MINOR DENT, SCRATCHES               | الصبغ                      |
| 01.C Sign of side accident  |   | وجود مؤشر لحادث في الجانب  |
| 01.D Sign of front accident |   | وجود مؤشر لحادث في المقدمة |
| 01.E Sign of back accident  |   | وجود مؤشر لحادث في الخلف   |
| 01.F Other                  | FRONT FENDER FRAME, RADITOR SUPPORT ,BUMPER FRAME, BULK HEAD REPAIRED | اخري                       |
| 01.G Doors                  | RIGHT SIDE OUTER COVER MISSING  | أبواب                      |
| O1.H Floor                  | BOTH SIDE RUNNING BOARD, REAR QUATER PANEL REPAIRED & BACK PANEL DENT | الارضية                    |

 02 Lights

02.A Warning Light WARNING LIGHT ON IN DISPLAY

O3 Interior Condition الحاله الداخليه

O3.A Air BagAIR BAG DAMAGEDO3.B AC ConditionOKO3.C Roof CeilingLOOSE

| DEFECT                      |   |                |
|-----------------------------|---|----------------|
| 04 Tires and Rims Condition |   | الاطارات       |
| 04.A Front Tyre             | BOTH SIDE 2019  | الاطار الامامي |
| 04.B Rear Tyre              | BOTH SIDE 2019  | الاطار الخلفي  |
| 05 Chassis Condition        |   | الشاصي         |
| 05.A Chassis                | FRONT RIGHT SIDE CHASSIS REPAIRED, BOTH SIDE BEND<br>& REAR RIGHT SIDE REPAIRED | الشاسيه        |
| 06 Suspension System        |   | ممتص الصدمات   |
| O6.A Arms                   | REAR LEFT SIDE CONTROL ARM ALIGN REPAIRED & MINOR BEND                          | ازرع           |

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate,
   Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

# **Test Certificate**









| Plate Details:   |               | V                 | V 58674 Dubai Private |           |  |
|------------------|---------------|-------------------|-----------------------|-----------|--|
| Chassis No:      |               | 1FA6P8CF9L5168883 |                       |           |  |
| Vehicle Make:    |               | FORD              |                       |           |  |
| Vehicle Model:   |               | MUSTANG           |                       |           |  |
| Vehicle Class:   |               | Light Vehicle     |                       |           |  |
| Body Type:       |               | Coupe             |                       |           |  |
| Fuel:            |               | Benzene           |                       |           |  |
| Color:           |               | Blue              |                       |           |  |
| Drive Direction: |               | -                 |                       |           |  |
| Dimensions       | : (H x W x L) | -                 | - x x                 |           |  |
| Current Odo      | meter :       | 2                 | 927 Kms.              |           |  |
| Origin :         | United States |                   | Model Year :          | 2020      |  |
| Gear Type:       | Automatic     |                   | Engine Size:          | 5000 CC   |  |
| Engine No:       | NILL          |                   | Horse                 | 435       |  |
| Axles No:        | 2             |                   | Power:                |           |  |
| No Of            | 2             |                   | Cylinders:            | 8         |  |
| Doors :          |               |                   | No Of Seats:          | 4         |  |
| G. V. W. :       | 2000 Kgs.     |                   | Empty<br>Weight:      | 1500 Kgs. |  |

Certificate Number: 5-TAS-2022-17149991 Inspection Date: 05-07-2022 Certificate Print Date : 05-07-2022 Services: Registration Test Vehicle Testing Partner: Tasieel Vehicle Testing Center: Tasjeel Al Aweer Total Time Taken: 11 min 33 sec **Appointment Ref** Number: Start 12:26 End Time: 12:38 Time: Token No.: 152 Lane: 01 Prints No: 1 Attempt: 1

# Carbon footprint



Thank you! You are environment protector

# Estimated Vehicle Consumption (Rate in 12 Months)







0.3 ton Carbon footprint

Distance per year

per year

Fuel cost per year

per year

#### **Parameter Readings**

Vehicle on Petrol HC

Reading O PPM VOL

Service brake imbalance on front axle 8 %

Service brake imbalance on rear axle 12 %

Parking brake imbalance between LHS and RHS 12 %

**Vehicle on Petrol CO** Reading 0%

### **Inspection Remarks:**

FRONT RIGHT7RR R/S ESIDE MEMBER.REAR BOTH SIDE CROSS MEMBER REPAIRED HAVE PASSED CCM REPORT AND FRONT BOTH SIDE FENDER FRAME SUPPORT, BOTH SIDE RUNNING BOARD, ROCKER PANEL, BOTH SIDE QUARTER PANEL, FLOORING, COMPARTMENT PANEL, **DOOR POST & B PILLAR REPAIRED** 

#### **Payment Details**

Inspection Performed by **Payment Method Transaction Number Service Fees** 17149991 62439 Cash AED 170 Collected on 05/07/2022 Parking Slot No **Service Name** Attempt Received by **Registration Test** Sittu Paloth Sreesan Paloth

- 1 This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service. Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.
- تستخدم هذه الشهادة حصرا في العمليات الخاصة بالترخيص الفني للمركبة. لا يعتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلاف عملية ترخيص المركبة. لا تتحمل الجهةً المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة وأحدة فقط خلال .30 يوم من تاريخ الفحص



This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.