CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2906106
Transaction Date	28 Oct 2026, 10:10:51
Site Name	840 - Emirates Auctions
Transaction Number	16997268 (CC10010) (CC10010)



Vehicle Details

Chassis Number	WDBUF87X28*******
Specification	Imported
Make	Mercedes
Model	E 350
Model Year	2008
Color	Black
Mileage	N/A NA
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition	Remarks	الحالة
01 Body		**جسم المركبة**
01.A Fenders	FRONT BOTH SIDE REPAINTED PORTION REPAIRED ,REFITTED.	مدكار
01.B Paint	BODY PORTION REPAINTED, PORTION REPAIRED DENTS, SCRATCHES , PORTION RUSTY, PORTION FADED	الصبغ
01.C Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY.	صدأ
01.D Floor	UNDER FLOOR CHASSIS COMPLETE COVERED COVER PORTION CUT ,CHECKED ONLY VISIBLE AREA	الارضية
01.E Bumper	MISALIGN,SCRATCHES , LOOSE ,PORTION DAMAGED.	دعامية
01.F Windshield	FRONT CRACKED .	زجاج
01.G Bonnet	REPAINTED PORTION REPAIRED.	غطاء المحرك
01.H Trunk	NOT OPEN ,PORTION REPAINTED .	صندوق
01.I Sign of front accident	FENDER FRAME ,BULKHEAD REPAIRED ASSEMBLY REFITTED .	وجود مؤشر لحادث في المقدمة
01.J Sign of back accident	BUMPER FRAME MISSING ,CRASH BOX BACK PANEL REPAIRED.	وجود مؤشر لحادث في الخلف
02 Chassis Condition		**الشاصي**
02.A Chassis	FRONT CHASSIS COVERED OILY MUDDY PORTION DENT ,REAR RIGHT SIDE EXTENSION END DENT .	الشاسيه
03 Engine Condition		**المحرك**
03.A Mount	BUSHES CRACKED .	كرسي
03.B Engine Visual Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED ,REFITTED OIL LEAK,PARTS RUSTY	الحالة النظريه للمحرك

Condition	Remarks	الحالة
04 Seats Condition		المقاعد
04.A Seat Condition	SIDE COVER PORTION LOOSE.	حالة المقاعد
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	NOT CHECKED ,REFITTED,OIL LEAK ,COMPONENT PARTS RUSTY .	الحالة النظريه للجير
05.B Road Test	NOT CHECKED .	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2024 CRACKED WORN OUT .	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2024 CRACKED .	الاطار الخلفي
06.C Rims Condition	DENTS SCRATCHES .	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	LENS FADED, ALL LIGHTS NOT CHECK	الاضاءة الرئيسية
08 Brake Condition		الفرامل
08.A Disc&Drum	PARTS RUSTY.	دسك وطنابير الفرامل
09 Suspension System		ممتص الصدمات
09.A Shock Absorber	LEAK WEAK .	ممتص الصدمات
09.B Arms	BUSHES CRACKED .	ازرع
10 Steering Condition		المقود
10.A Steering Boot	CRACKED.	ربلة المقود
10.B Steering Box	OIL LEAK .	جهاز المقود
11 Interior Condition		الحاله الداخليه
11.A Other	INTERIOR PARTS GETTING RUSTY ,SIGN OF FLOODED	اخري
11.B AC Condition	NOT CHECKED .	المكيف
11.C FLoor Matting	CENTER CONSOLE BOX DAMAGED.	فرش الأرضيه
11.D Dash Board	PORTION LOOSE.	لوحة القياده
11.E Sun Visor	LOOSE.	حاجب الشمس
11.F Odometer reading	NOT CHECKED,	قراءة عداد المسافات
11.G Door Panel	WORN OUT PORTION LOOSE.	لوحة بطانة الباب
11.H Steering Wheel and control buttons	WORN OUT .	عجلة القيادة وازرار التحكم
11.I Gear Shifting Lever	KNOB WORN OUT.	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions الشروط والأحكام

The inspection report is valid and shows the

vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر **wecare@carscheck.ae**