



TEST CERTIFICATE

Site Number **840-Emirates Auctions** Transaction Date **25 Sep 2022, 12:27:23**
 Transaction Number **46263064 (CC10006)** Queue Number **595354**



Chassis Number **SALFA2BG8DH322107**
 Engine Number
 Vehicle Class **Car**
 Manufacturer **Land Rover**
 Model **LR 2**
 Model Year **2013**
 Color **White**
 Mileage **226036 Km**
 Fuel Type **Petrol**
 No. Of Cylinders **4**
 Specification **GCC Specification**

DEFECT	REMARKS	
01 Interior Condition		الحاله الداخليه
01.A Mirror	RIGHT SIDE FOLDING & ADJUSTMENT NOT WORK.	المرايا
01.B Roof Ceiling	PORTION LOOSE.	بطانه السقف
01.C Other	ROOF LIGHT COVER LOOSE.	اخرى
01.D AC Condition	OK,BLOWER ADJUSTER NOT WORKING PROPERLY .	المكيف
01.E Dash Board	CRACKED.	لوحة القيادة
01.F Power Window Switch	RIGHT SIDE BOTH NOT WORKING.	مفتاح النافذه
02 Seats Condition		المقاعد
02.A Seat Condition	PORTION CRACK.	حالة المقاعد
03 Tires and Rims Condition		الاطارات
03.A Front Tyre	BOTH SIDE 2021	الاطار الامامي
03.B Rear Tyre	BOTH SIDE 2020	الاطار الخلفي
04 Body		جسم المركبة
04.A Paint	MINOR DENTS SCRATCHES.	الصبغ
05 Transmission Condition		الجير
05.A Road Test	NOT CHECK	فحص علي الطريق

DEFECT	REMARKS	
05.B Visual Gear Box Condition	OPEN REFITTED.	حالة الجير النظري
06 Engine Condition		المحرك
06.A Visual Engine Condition	REFITTED OIL WET.	حالة المحرك النظري
06.B Mount	RIGHT SIDE TOP MOUNT BUSH CUT.	كرسي
07 Suspension System		ممتص الصدمات
07.A Ball Joint	LINK ROD BALL JOINT WORN OUT.LOWER ARM BALL JOINT BOOT CUT LEAKING.	مفصل كروي
07.B Arms	LOWER ARM BUSHES CRACK.	ازرع
08 Chassis Condition		الشاسي
08.A Chassis	CHECKED VISIBLE AREA OK.	الشاسيه
09 Steering Condition		المقود
09.A Axel	BOOT LEAKING.	اكسلات

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.