

Queue Number 2784387

Transaction Date 22 Sep 2026, 12:58:24

Site Name
840 - Emirates AuctionsTransaction Number
16562277 (CC10013) (CC10013)

Vehicle Details

Chassis Number	WP1AA2A50P*****
Specification	Imported
Make	Porsche
Model	Macan
Model Year	2023
Color	Silver
Mileage	N/A NA
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
-----------	---------	--------

01 Body

جسم المركبة

01.A Paint	PORTION REPAIRED, PORTION REPAINTED, DENTS, SCRATCHES , BODY HAVING CERAMIC COATING	الصبغ
01.B Rusty	UNDER BODY PARTS,SUSPENSION GETTING RUSTY	صدأ
01.C Floor	UNDER FLOOR PORTION COVERED DENT ,MUDDY	الارضية
01.D Bumper	MISALIGN PORTION SCRATCHES	دعامية
01.E Trunk	NOT CHECKED	صندوق
01.F Fuel Tank	DENT	خزان الوقود
01.G Sign of front accident	FRONT BUMPER FRAME , RADIATOR SUPPORT BULK HEAD ASSEMBLY REFITTED	وجود مؤشر لحادث في المقدمة
01.H Sign of back accident	BACK PANEL ,QUARTER PANEL ,COMPARTMENT FLOOR REPAIRED,DENT	وجود مؤشر لحادث في الخلف

02 Chassis Condition

الشاسي

02.A Chassis	REAR BOTH SIDE EXTENSION REPAIRED / REAR LEFT SID FLOOR LOADING POINT AREA DENT / PRTION OPEN DETACHED	الشاسيه
--------------	--	---------

03 Engine Condition

المحرك

03.A Engine Visual Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED , MUDDY , PARTS GETTING RUSTY , KEY MISSING	الحالة النظرية للمحرك
------------------------------	--	-----------------------

04 Transmission Condition

الجير

04.A Gear Box Visual Condition	NOT CHECKED MUDDY PARTS GETTING RUSTY	الحالة النظرية للجير
--------------------------------	---------------------------------------	----------------------

Condition	Remarks	الحالة
04.B Road Test	NOT CHECKED	فحص علي الطريق
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	2022 DRY CRACK	الاطار الامامي
05.B Rear Tyre	2022 DRY CRACK	الاطار الخلفي
06 Brake Condition		الفرامل
06.A Disc&Drum	RUSTY	دسك وطناير الفرامل
07 Suspension System		ممتص الصدمات
07.A Shock Absorber	LEAK	ممتص الصدمات
07.B Arms	ARM BUSHES DRY CRACK	ازرع
08 Interior Condition		الحالة الداخلية
08.A Other	INTERIOR PARTS GETTING RUSTY	اخرى
08.B AC Condition	NOT CHECKED	المكيف
08.C Dash Board	GETTING FADED PORTION WORN OUT	لوحة القيادة
08.D Odometer reading	NOT CHECKED	قراءة عداد المسافات
08.E Steering Wheel and control buttons	GETTING WORN OUT	عجلة القيادة وازرار التحكم

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

For complaints and inquiries reach out to us on wecare@carscheck.ae

لشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae