CAR CHECK

# شهادة فحص مركبة
# Vehicle Test Certificate

| | |
|---|---|
| Queue Number | 2945754 |
| Transaction Date | 04 Nov 2026, 14:27:39 |
| Site Name | 840 - Emirates Auctions |
| Transaction Number | 74224628 (CC10010) (CC10010) |




## Vehicle Details

| | |
|---|---|
| Chassis Number | LJ12EKS30P******* |
| Specification | GCC Specification |
| Make | JAC |
| Model | JS4 |
| Model Year | 2023 |
| Color | Red |
| Mileage | 44098 Km |
| Fuel Type | Petrol |
| Transmission Type | |
| No. Of Cylinders | 4 |

| Condition | Remarks | الحالة |
|---|---|---|
| **01 Body** | | **جسم المركبة** |
| 01.A Fenders | REAPIRED ,DENT REFITTED MISALIGNED . | مدكار |
| 01.B Paint | BODY PORTION REPAINTED PORTION REPAIRED,MINOR DENTS SCRATCHES . | الصبغ |
| 01.C Rusty | UNDER BODY SUSPENSION PARTS GETTING RUSTY. | صدأ |
| 01.D Floor | UNDER FLOOR PORTION DENT ,MUDDY., | الارضية |
| 01.E Bumper | FRONT BUMPER DAMAGED. | دعامية |
| 01.F Windshield | FRONT WINDSHIELD BROKEN | زجاج |
| 01.G Bonnet | REPAINTED DENT MISALIGNED. | غطاء المحرك |
| 01.H Door Handle &Lock | FRONT LEFT OUTER HANDLE DAMAGED | مقابض الأبواب والأقفال |
| 01.I Sign of front accident | FRONT ASSEMBLY DAMAGED /BUMPER FRAME CRACKED. | وجود مؤشر لحادث في المقدمة |
| **02 Chassis Condition** | | **الشاصي** |
| 02.A Chassis | FRONT CHASSIS END MINOR DENT CHASSIS COVERED. | الشاسيه |
| 02.B Other | NEED TO REMOVE FENDER UNDER COVER FOR INSPECTION | اخري |
| **03 Engine Condition** | | **المحرك** |
| 03.A Engine Visual Condition | COMPONENT PARTS RUSTY ,SHAKING. | الحالة النظريه للمحرك |
| **04 Transmission Condition** | | **الجير** |
| 04.A Gear Box Visual Condition | COMPONENT PARTS RUTY. | الحالة النظريه للجير |

| Condition | Remarks | الحالة |
|---|---|---|
| 04.B Road Test | NOT CHECKED. | فحص علي الطريق |
| **05 Tires and Rims Condition** | | **الاطارات** |
| 05.A Front Tyre | BOTH SIDE 2023 CRACKED DAMAGED. | الاطار الامامي |
| 05.B Rear Tyre | BOTH SIDE 2023 CRACKED . | الاطار الخلفي |
| **06 Lights** | | **الاضاءة** |
| 06.A Head Light | BOTH SIDE HEAD LIGHT ASSEMBLY BROKEN DAMAGED . | الاضاءة الرئيسية |
| 06.B Warning Light | EXTRA WARNING LIGHT ON IN CLUSTER | ضوء تحذير |
| **07 Brake Condition** | | **الفرامل** |
| 07.A Brake Pedal | SPONGY/ | دواسة الفرامل |
| 07.B Disc&Drum | RUSTY. | دسك وطنابير الفرامل |
| **08 Interior Condition** | | **الحاله الداخليه** |
| 08.A Other | INTERIOR PARTS GETTING RUSTY. | اخري |
| 08.B AC Condition | NOT COOLING. | المكيف |
| 08.C Dash Board | DAMAGED. | لوحة القياده |
| 08.D Air Bag | DAMAGED . | وسائد هوائية |
| 08.E Steering Wheel and control buttons | DAMAGED | عجلة القيادة وازرار التحكم |

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
**carcheck.ae/certificate**

## Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

## الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
**wecare@carscheck.ae**