

Queue Number	2865399	Transaction Date	13 Oct 2026, 13:40:20
Site Name	840 - Emirates Auctions	Transaction Number	95046240 (CC10026) (CC10026)



Vehicle Details

Chassis Number	JN1VAZR50Z*****
Specification	GCC Specification
Make	Nissan
Model	Pathfinder
Model Year	2004
Color	Red
Mileage	N/A Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition	Remarks	الحالة
-----------	---------	--------

01 Body		جسم المركبة
01.A Fenders	FRONT BOTH SIDE & REAR RIGHT SIDE REPAINTED PORTION REPAIRED ,BOTH SIDE REFITTED	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED , DENT SCRATCHES , PORTION FADED GETTING RUSTY	الصبغ
01.C Doors	REAR BOTH SIDE DOOR BEADING MISSING	أبواب
01.D Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.E Floor	UNDER FLOOR PARTS MINOR DENT , MUDDY	الارضية
01.F Bumper	MISALIGN , SCRATCHES DENT	دعامية
01.G Bonnet	REPAINTED PORTION REPAIRED , MISALIGN	غطاء المحرك
01.H Trunk	REPAINTED PORTION REPAIRED , PORTION FADED	صندوق
01.I Sign of front accident	BUMPER FRAME , INNER FENDER FRAME REPAIRED	وجود مؤشر لحادث في المقدمة
01.J Sign of side accident	FRONT RIGHT SIDE FENDER BADLY DAMAGE , DENT	وجود مؤشر لحادث في الجانب
01.K Sign of back accident	BACK PANEL , BUMPER FRAME REPAIRED , DENT	وجود مؤشر لحادث في الخلف

02 Chassis Condition		الشاسي
02.A Chassis	CHASSIS PORTION COVER , CHECK VISIBLE AREA ONLY , MUDDY OILLY , GETTING RUSTY	الشاسيه
02.B Chassis Number	CHASSIS NUMBER AREA REPAIRED (SUSBECT CUT) #VIN STICKER DAMAGE , CHECK ONLY ON CHASSIS # ENGRAVED	رقم القاعدة

03 Engine Condition	المحرك
---------------------	--------

Condition	Remarks	الحالة
03.A Engine Visual Condition	ENGINE NOT STARTING , ALL SYSTEM NOT CHECK , PARTS REFITTED GETTING RUSTY , MUDDY	الحالة النظرية للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	PORTION WORN OUT , REAR SEAT FOAM MISSING	حالة المقاعد
05 Exhaust System		نظام العادم
05.A Modification	EXHAUST PIPE CUT REWELDED	تعديلات
06 Transmission Condition		الجير
06.A Gear Box Visual Condition	NOT CHECK , PARTS REFITTED GETTING RUSTY , SIGN OF WET , MUDDY	الحالة النظرية للجير
07 Tires and Rims Condition		الاطارات
07.A Front Tyre	BOTH SIDE 2019 CRACK EXPIRED & LEFT SIDE DAMAGE	الاطار الامامي
07.B Rear Tyre	BOTH SIDE 2021 CRACK EXPIRED , BOTH SIDE DAMAGE	الاطار الخلفي
07.C Rims Condition	DENTS SCRATCHES	حالة الجنوط
08 Lights		الاضاءة
08.A Head Light	RIGHT SIDE LEN GETTING FADED , ALL LIGHTS NOT CHECK	الاضاءة الرئيسية
08.B Indicator & Hazard light	RIGHT SIDE INDICATOR LIGHT HOUSING BADLY DAMAGE	الاشارات
09 Brake Condition		الفرامل
09.A Brake Pedal	RUSTY	دواسة الفرامل
10 Suspension System		ممتص الصدمات
10.A Arms	BUSHES CRACK	ازرع
10.B Other	REAR LEFT SIDE CONTROL ARM MINOR BEND	اخرى
10.C Stabilizer Bar And Link Rod	BOOT CRACK	عمود التوازن و مثبت عمود التوازن
11 Steering Condition		المقود
11.A Tie Rod End	BOOT CRACK	مؤخرة الرودادات
12 Interior Condition		الحالة الداخليه
12.A Other	CENTER CONSOLE PANEL WORN OUT , INTERIOR PARTS GETTING RUSTY , SIGN OF FLOODED	اخرى
12.B Mirror	BOTH SIDE VIEW MIRROR GETTING FADED	المرايا
12.C AC Condition	NOT CHECK , CONTROL PANEL SWICTH GETTING FADED	المكيف
12.D Roof Light	HOUSING DAMAGE	أنارة السقف
12.E Power Window Switch And Glass	MAIN SWICTH BUTTON FADED	مفتاح النافذه و الزجاج
12.F Floor Matting	DIRTY	فرش الأرضيه
12.G Audio	LCD SCREEN FADED	صوتيات
12.H Dash Board	DAMAGE	لوحة القيادة
12.I Roof Ceiling	FABRIC PORTION DAMAGE	بطانه السقف
12.J Sun Visor	RIGHT SIDE MIRROR COVER DAMAGE	حاجب الشمس

Condition	Remarks	الحالة
12.K Odometer reading	NOT CHECK	قراءة عداد المسافات
12.L Door Panel	PORTION DAMAGE	لوحة بطانة الباب
12.M Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
12.N Gear Shifting Lever	PORTION WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص. ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on wecare@carscheck.ae

للسكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae