



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	28 Nov 2021, 17:52:43
Transaction Number	30928530 (CC10006)	Queue Number	312309



Chassis Number	JMYSRCS1A9U700843
Engine Number	
Vehicle Class	Car
Manufacturer	Mitsubishi
Model	Lancer
Model Year	2009
Color	Silver
Mileage	150610 Km
Fuel Type	Petrol
No. Of Cylinders	4
Specification	GCC Specification

DEFECT	REMARKS	
01 Body		جسم المركبة
01.A Fenders	PORTION REPAIRED & REPAINTED	مدكار
01.B Paint	TOTALLY REPAINTED , PORTION REPAIRED & DENTS, SCRATCHES ON BODY	الصبغ
01.C Doors	PORTION REPAIRED & REPAINTED	أبواب
01.D Bonnet	REPAINTED	غطاء المحرك
01.E Bumper	REPAINTED	دعامية
01.F Trunk	PORTION REPAINTED	صندوق
01.G Roof	REPAINTED	السقف
01.H Rusty	UNDER BODY PARTS, SUSPENSION , CHASSIS, FLOOR GETTING RUSTY	صدأ
01.I Floor	UNDER FLOOR RUST PROOFED	الارضية
02 Transmission Condition		الجير
02.A Road Test	NOT CHECK	فحص علي الطريق
02.B Gear Box	OIL LEAK	الجير
03 Chassis Condition		الشاسي
03.A Chassis	OK	الشاسيه

DEFECT	REMARKS	
04 Brake Condition		الفرامل
04.A Disc&Drum	GETTING RUSTY	دسك وطنابير الفرامل
05 Suspension System		ممتص الصدمات
05.A Suspension Subframe	SUSPENTION SUB FRAME GETTING RUSTY	
05.B Arms	FRONT LOWER ARM BUSHES CRACKED	ازرع
06 Engine Condition		المحرك
06.A Engine Condition	OK	حالة المحرك
07 Lights		الاضاءة
07.A Head Light	OK	الاضاءة الرئيسية
07.B Tail Light	LEFT SIDE CRACKED , LOOSE	الدائرة
08 Wipers and Arms		المساحات
08.A Wiper Arm &Blade	WORN OUT	ازرع المساحات والشفرات
09 Tires and Rims Condition		الاطارات
09.A Front Tyre	LEFT SIDE 2019 & RIGHT SIDE 2017 EXPIRED	الاطار الامامي
09.B Rear Tyre	LEFT SIDE 2019 & RIGHT SIDE 2018 CRACKED	الاطار الخلفي
09.C Spare Tire &Tools	SPARE TIRE&TOOLS MISSING	الاطار الاحتياطي و العدة
10 Interior Condition		الحاله الداخليه
10.A Mirror	LEFT SIDE MISSING	المرايا
10.B AC Condition	NOT COOLING	المكيف
10.C Power Window Switch	NOT WORKING	مفتاح النافذه
10.D Door Panel	FRONT BOTH SIDE PORTION DAMAGE	لوحة بطانة الباب
11 Steering Condition		المقود
11.A Steering Box	STEERING HARD	جهاز المقود
11.B Other	STABILIZER LINK BUSHES DRY CRACKED	اخرى
11.C Tie Rod End	BUSHES CUT	مؤخرة الرودادات

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.