

Queue Number 2792355

Transaction Date 24 Sep 2026, 16:51:06

Site Name  
840 - Emirates AuctionsTransaction Number  
58131177 (CC10009) (CC10012)

## Vehicle Details

|                   |                   |
|-------------------|-------------------|
| Chassis Number    | WBAJL1A09L*****   |
| Specification     | GCC Specification |
| Make              | BMW               |
| Model             | 520i TOURING      |
| Model Year        | 2020              |
| Color             | Blue              |
| Mileage           | 119453 Km         |
| Fuel Type         | Petrol            |
| Transmission Type |                   |
| No. Of Cylinders  | 4                 |

## Condition

## Remarks

## الحالة

## 01 Body

## جسم المركبة

|                    |                                                              |
|--------------------|--------------------------------------------------------------|
| 01.A Paint         | BODY PORTION REPAINTED PORTION REPAIRED MINOR DENT SCRATCHES |
| 01.B Doors         | REAR LEFT SIDE REPAINTED PORTION REPAIRED                    |
| 01.C Rusty         | UNDER BODY PARTS GETTING RUSTY                               |
| 01.D Floor         | FLOOR CHASSIS NOT VISIBLE COMPLETELY COVERED                 |
| 01.E Trunk         | REPAINTED PORTION REPAIRED , AUTO NOT WORKING PROPERLY       |
| 01.F Vehicle Model | 520i                                                         |

الصبغ

أبواب

صدأ

الارضية

صندوق

طراز المركبة

## 02 Chassis Condition

## الشاسي

|              |                                                         |
|--------------|---------------------------------------------------------|
| 02.A Chassis | CHASSIS COMPLETELY COVERED CHECKED VISIBLE AREA ONLY/OK |
|--------------|---------------------------------------------------------|

الشاسيه

## 03 Engine Condition

## المحرك

|                              |                                 |
|------------------------------|---------------------------------|
| 03.A Engine Visual Condition | OIL LEAK REFITTED GETTING RUSTY |
|------------------------------|---------------------------------|

الحالة النظرية للمحرك

## 04 Seats Condition

## المقاعد

|                     |                              |
|---------------------|------------------------------|
| 04.A Seat Condition | DRIVER SEAT SIDE COVER LOOSE |
|---------------------|------------------------------|

حالة المقاعد

## 05 Transmission Condition

## الجير

|                                |                                                |
|--------------------------------|------------------------------------------------|
| 05.A Gear Box Visual Condition | REFITTED OIL WET MINOR JERKING , GETTING RUSTY |
|--------------------------------|------------------------------------------------|

الحالة النظرية للجير

|                |             |
|----------------|-------------|
| 05.B Road Test | NOT CHECKED |
|----------------|-------------|

فحص علي الطريق

| Condition                               | Remarks                                        | الحالة                     |
|-----------------------------------------|------------------------------------------------|----------------------------|
| <b>06 Tires and Rims Condition</b>      |                                                | <b>الاطارات</b>            |
| 06.A Front Tyre                         | RIGHT SIDE 2023 , LEFT SIDE 2026               | الاطار الامامي             |
| 06.B Rear Tyre                          | BOTH SIDE 2021 EXPIRED                         | الاطار الخلفي              |
| <b>07 Suspension System</b>             |                                                | <b>ممتص الصدمات</b>        |
| 07.A Arms                               | BUSHES CRACKED                                 | ازرع                       |
| <b>08 Interior Condition</b>            |                                                | <b>الحاله الداخليه</b>     |
| 08.A Other                              | INNER PARTS GETTING RUSTY                      | اخرى                       |
| 08.B AC Condition                       | NOT COOLING , GRILL ADJUSTMENT PORTION MISSING | المكيف                     |
| 08.C Power Window Switch And Glass      | LOCK BUTTON GLASS NOT WORKING                  | مفتاح النافذه و الزجاج     |
| 08.D Steering Wheel and control buttons | WORN OUT                                       | عجلة القيادة وازرار التحكم |

you can verify the validity of the certificate via the link: [carcheck.ae/certificate](https://carcheck.ae/certificate)



يمكنك التحقق من صحة الشهادة عبر الرابط [carcheck.ae/certificate](https://carcheck.ae/certificate)

## Terms & Conditions

## الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

For complaints and inquiries reach out to us on [wecare@carscheck.ae](mailto:wecare@carscheck.ae)

لشكاوي والمقترحات يمكنك التواصل معنا عبر [wecare@carscheck.ae](mailto:wecare@carscheck.ae)