CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2877840
Transaction Date	19 Oct 2026, 12:12:46
Site Name	840 - Emirates Auctions
Transaction Number	67759222 (CC10010) (CC10010)



Vehicle Details

Chassis Number	KL1GM5EU3D*******
Specification	GCC Specification
Make	Chevrolet
Model	Malibu
Model Year	2013
Color	Silver
Mileage	N/A Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	FRONT RIGHT SIDE DAMAGE /BOTH SIDE REPAINTED PORTION REPAIRED.	مدكار
01.B Paint	BODY PORTION REPAINTED, PORTION REPAIRED DENTS, SCRATCHES , PORTION RUSTY, PORTION FADED	الصبغ
01.C Rusty	UNDER BODY PARTS,SUSPENSION GETTING RUSTY	صدأ
01.D Floor	UNDER FLOOR PORTION DENT .	الارضية
01.E Bumper	BUMPER MISALIGN ,SCRATCHES ,PORTION DAMAGED.	دعامية
01.F Bonnet	REPAIRED REPAINTED REFITTED/	غطاء المحرك
01.G Sign of front accident	FRONT BUMPER FRAME , RADIATOR SUPPORT BULK HEAD ,FENDER FRAME REPAIRED.	وجود مؤشر لحادث في المقدمة
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS COMPLETE COVERED ,OILY MUDDY NOT VISIBLE PROPERLY,CHECKED ONLY VISIBLE AREA,FRONT END PORTION DENT .	الشاسيه
03 Engine Condition		المحرك
03.A Engine Visual Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED ,REFITTED OIL LEAK,PARTS RUSTY	الحالة النظريه للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	DIRTY LOOSE.	حالة المقاعد
05 Transmission Condition		الجير

Condition	Remarks	الحالة
05.A Gear Box Visual Condition	NOT CHECKED ,REFITTED,OIL LEAK ,COMPONENT PARTS RUSTY .	الحالة النظريه للجير
05.B Road Test	NOT CHECKED.	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH AID 2024 CRACKED WORN OUT	الاطار الامامي
06.B Rear Tyre	BOTH SIDE EXPIRED CRACKED DAMAGED	الاطار الخلفي
06.C Rims Condition	DENTS SCRATCHES	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	RIGHT SIDE HEAD LIGHT DAMAGED ,LENS FADED ALL LIGHT NOT CHECKED	الاضاءة الرئيسية
08 Brake Condition		الفرامل
08.A Disc&Drum	PARTS RUSTY.	دسك وطنابير الفرامل
09 Suspension System		ممتص الصدمات
09.A Shock Absorber	LEAK .	ممتص الصدمات
09.B Arms	BUSHES CUT .	ازرع
10 Steering Condition		المقود
10.A Steering Boot	CUT .	ربلة المقود
10.B Steering Box	OIL LEAK .	جهاز المقود
11 Interior Condition		الحاله الداخليه
11.A Other	INTERIOR PARTS RUSTY,SIGN OF FLOODED.	اخري
11.B Mirror	LOOSE FADED.	المرايا
11.C AC Condition	NOT CHECKED .	المكيف
11.D Roof Ceiling	PORTION LOOSE.	بطانه السقف
11.E Odometer reading	NOT CHECKED .	قراءة عداد المسافات
11.F Door Panel	WORN OUT PORTION LOOSE.	لوحة بطانة الباب
11.G Steering Wheel and control buttons	WORN OUT .	عجلة القيادة وازرار التحكم
11.H Gear Shifting Lever	KNOB WORN OUT .	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة،
كما لا تضمن بموجب هذه الشهادة صلاحية المركبة
.للتسجيل من عدمه

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae