CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2899693
Transaction Date	29 Oct 2026, 13:23:46
Site Name	840 - Emirates Auctions
Transaction Number	54333646 (CC10010) (CC10011)



Vehicle Details

Chassis Number	JTHBN36F06*******
Specification	Imported
Make	Lexus
Model	LS 430
Model Year	2006
Color	White
Mileage	193658 Miles
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	8

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	FRONT LEFT SIDE REFITTED	مدكار
01.B Paint	BODY REPAINTED,PORTION REPAIRED,MINOR DENT SCRATCHES,PORTION GETTING FADED RUSTY	الصبغ
01.C Doors	REAR LEFT SIDE REFITTED	أبواب
01.D Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY.	صدأ
01.E Floor	UNDER FLOOR CHASSIS COMPLETE COVERED COVER PORTION CUT ,CHECKED ONLY VISIBLE AREA	الارضية
01.F Bumper	MISALIGN PORTION DAMAGED	دعامية
01.G Bonnet	MISALIGN NOT CLOSE	غطاء المحرك
01.H Trunk	NOT OPEN	صندوق
01.I Door Handle &Lock	REAR LEFT SIDE DOOR OUTER HANDLE DAMAGED PART MISSING	مقابض الأبواب والأقفال
01.J Sign of front accident	BUMPER FRAME ,BULKHEAD DENT .	وجود مؤشر لحادث في المقدمة
02 Chassis Condition		الشاصي
02.A Chassis	FRONT BOTH SIDE CHASSIS BEND KINK . CHASSIS OILY MUDDY , COVERED.	الشاسيه
03 Engine Condition		المحرك
03.A Engine Visual Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED ,REFITTED OIL LEAK,PARTS RUSTY	الحالة النظريه للمحرك
04 Seats Condition		المقاعد

Condition	Remarks	الحالة
04.A Seat Condition	COVER PORTION CUT WORN OUT	حالة المقاعد
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	NOT CHECKED ,REFITTED,OIL LEAK ,COMPONENT PARTS RUSTY .	الحالة النظريه للجير
05.B Road Test	NOT CHECKED .	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2024 CRACK	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2023 CRACK	الاطار الخلفي
06.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	LENS FADED, ALL LIGHTS NOT CHECK	الاضاءة الرئيسية
08 Brake Condition		الفرامل
08.A Disc&Drum	PARTS RUSTY.	دسك وطنابير الفرامل
09 Suspension System		ممتص الصدمات
09.A Shock Absorber	LEAK .	ممتص الصدمات
09.B Arms	BUSHES CUT .	ازرع
10 Steering Condition		المقود
10.A Steering Boot	CUT .	ربلة المقود
10.B Steering Box	OIL LEAK .	جهاز المقود
11 Interior Condition		الحاله الداخليه
11.A Other	CENTER CONSOLE BOX COVER WORN OUT	اخري
11.B AC Condition	NOT CHECK	المكيف
11.C Roof Light	SUNGLASSES BOX LOCK DAMAGED	أنارة السقف
11.D Dash Board	PORTION WORN OUT & DASHBOARD SIDE HAVING BURNING SMOKE . WIRING SHORTAGE.	لوحة القياده
11.E Door Panel	PORTION WORN OUT LOOSE	لوحة بطانة الباب
11.F Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
11.G Gear Shifting Lever	KNOB WORN OUT,SHIFT LOCK COVER MISSING	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة،
كما لا تضمن بموجب هذه الشهادة صلاحية المركبة
.للتسجيل من عدمه

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae