CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2945030
Transaction Date	05 Nov 2026, 16:46:12
Site Name	840 - Emirates Auctions
Transaction Number	31651493 (CC10026) (CC10026)



Vehicle Details

Chassis Number	2FMDK4KC3C*******
Specification	GCC Specification
Make	Ford
Model	Edge
Model Year	2012
Color	Red
Mileage	N/A NA
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	FRONT BOTH SIDE RIFITTED	مدكار
01.B Paint	BODY REPAINTED PORTION REPAIRED , DENT SCRATCHES , POTION FADED	الصبغ
01.C Doors	FRONT BOTH SIDE REFITTED	أبواب
01.D Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.E Floor	BOTH SIDE RUNNING BOARD PORTION REPAIRED , DENT	الارضية
01.F Bumper	BADLY DAMAGE , LOGO FADED	دعامية
01.G Bonnet	REPAINTED PORTION REPAIRED, REFITTED , PORTION STICKER	غطاء المحرك
01.H Other	INTERIOR MODIFIED , REFITTED	اخري
01.I Sign of back accident	TRUNK & BUMPER BADLY DAMAGE	وجود مؤشر لحادث في الخلف
01.J Vehicle Color	BLACK	لون المركبة
02 Chassis Condition		الشاصي
02.A Chassis	OK	الشاسيه
03 Engine Condition		المحرك
03.A Engine Visual Condition	ENGINE NOT STARTING , ALL SYSTEM NOT CHECK , PARTS REFITTED GETTING RUSTY	الحالة النظريه للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	LEATHER REPLACED , REFITTED , PORTION WORN OUT	حالة المقاعد

Condition	Remarks	الحالة
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	NOT CHECK , PARTS REFITTED GETTING RUSTY	الحالة النظريه للجير
05.B Road Test	NOT CHECK	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE CRACK	الاطار الامامي
06.B Rear Tyre	BOTH SIDE CRACK	الاطار الخلفي
06.C Other	MINOR DENT SCRATCHES	اخري
07 Wipers and Arms		المساحات
07.A Wiper Arm &Blade	REAR WIPER MISSING	ازرع المساحات والشفرات
08 Lights		الاضاءة
08.A Head Light	LENS FADED , ALL LIGHT NOT CHEK	الاضاءة الرئيسية
08.B Brake Light	LEFT SIDE DAMAGE	نور الفرامل
08.C Fog light	LEFT SIDE LEN FADED & RIGHT SIDE DAMAGE	كشاف الضباب
09 Interior Condition		الحاله الداخليه
09.A Other	CENTER CONSOLE BOX PORTION WORN OUT , INETERIOR PARTS GETTING RUSTY , SIGN OF FLOODED	اخري
09.B AC Condition	NOT CHECK	المكيف
09.C Dash Board	PORTION WORN OUT	لوحة القياده
09.D Door Panel	LEATHER REPLACED , PORTION WORN OUT	لوحة بطانة الباب
09.E Steering Wheel and control buttons	LEATHER REPLACED , PORTION WORN OUT	عجلة القيادة وازرار التحكم
09.F Gear Shifting Lever	PORTION WORN OUT	ذراع نقل السرعات
10 Engine Cooling System		نظام تبريد المحرك
10.A Coolant tank	EMPTY	خزان التبريد

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر

wecare@carscheck.ae