

Queue Number 2920488

Transaction Date 29 Oct 2026, 16:06:59

Site Name
840 - Emirates AuctionsTransaction Number
12382856 (CC10009) (CC10012)

Vehicle Details

Chassis Number	WDDZF4JB9J*****
Specification	Imported
Make	Mercedes
Model	E 300
Model Year	2018
Color	Black
Mileage	208853 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	LEFT SIDE BOTH REPAINTED PORTION REPAIRED , FRONT LEFT SIDE REFITTED	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED MINOR DENT SCRATCHES	الصبغ
01.C Doors	LEFT SIDE BOTH REPAINTED , REFITTED	أبواب
01.D Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.E Floor	FLOOR CHASSIS COVERED PORTION DENT	الارضية
01.F Bumper	MISALIGN	دعامية
01.G Bonnet	REPAINTED PORTION REPAIRED , REFITTED , SHOCK WEAK	غطاء المحرك
01.H Pillars	LEFT SIDE PILLAR REPAINTED , LEFT SIDE C / PILLAR ROCKER PANEL REPAIRED	القوائم
01.I Trunk	MISALIGN	صندوق
01.J Sign of front accident	FRONT BUMPER BULK HEAD ASSEMBLY REFITTED	وجود مؤشر لحادث في المقدمة

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS COMPLETELY COVERED CHECKED VISIBLE AREA ONLY OK	الشاسيه
02.B Other	REMOVE ALL UNDER FLOOR CHASSIS FENDER COVERS FOR RECHECK	اخرى

03 Engine Condition

المحرك

03.A Engine Visual Condition	MINOR OIL LEAK PARTS REFITTED GETTING RUSTY	الحالة النظرية للمحرك
------------------------------	---	-----------------------

04 Transmission Condition

الجير

Condition	Remarks	الحالة
04.A Gear Box Visual Condition	MINOR JERKING, GETTING RUSTY	الحالة النظرية للجير
04.B Road Test	NOT CHECKED	فحص علي الطريق
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	BOTH SIDE 2025	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2025	الاطار الخلفي
05.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
06 Lights		الاضاءة
06.A Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
07 Suspension System		ممتص الصدمات
07.A Arms	BUSHES CRACKED	ازرع
08 Steering Condition		المقود
08.A Tie Rod End	BOOT CUT	مؤخرة الرودادات
09 Interior Condition		الحالة الداخلية
09.A Other	INTERIOR PARTS GETTING RUSTY , (SING FO FLOOEDE) , INTERIOR REFITTED	اخرى
09.B AC Condition	OK	المكيف
09.C Floor Matting	PORTION LOOSE	فرش الأرضية
09.D Dash Board	LEATHER REPLACED	لوحة القيادة
09.E Sun Visor	BOTH SIDE MIRROR COVER BRACKET DAMAGED , LOOSE	حاجب الشمس
09.F Door Panel	PORTION LOOSE	لوحة بطانة الباب

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

For complaints and inquiries reach out to us on wecare@carscheck.ae

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae