CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2978262
Transaction Date	13 Nov 2026, 15:08:46
Site Name	840 - Emirates Auctions
Transaction Number	62415353 (CC10013) (CC10011)



Vehicle Details

Chassis Number	W1WV0GEZ2P*******
Specification	GCC Specification
Make	Mercedes
Model	Vito
Model Year	2023
Color	Black
Mileage	90332 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENT SCRATCHES	الصبغ
01.B Rusty	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY	صدأ
01.C Floor	UNDER FLOOR PORTION DIRTY	الارضية
01.D Bumper	MISALIGN	دعامية
01.E Bonnet	REPAINTED PORTION REPAIRED,REFITTED	غطاء المحرك
01.F Trunk	REFITTED	صندوق
01.G Door Handle &Lock	REAR BOTH SIDE DOOR OUTER AUTO LOCK HANDLE NOT WORKING	مقابض الأبواب والأقفال
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS PORTION COVERED CHECK VISIBLE AREA ONLY / OK	الشاسيه
03 Engine Condition		المحرك
03.A Engine Visual Condition	COMPONENTS REFITTED , PARTS GETTING RUSTY	الحالة النظريه للمحرك
04 Transmission Condition		الجير
04.A Gear Box Visual Condition	PARTS GETTING RUSTY	الحالة النظريه للجير
04.B Road Test	NOT CHECKED	فحص علي الطريق
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	BOTH SIDE 2026	الاطار الامامي

Condition	Remarks	الحالة
05.B Rear Tyre	BOTH SIDE 2023	الاطار الخلفي
05.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
06 Lights		الاضاءة
06.A Tail Light	GETTING FADED,RIGHT SIDE PORTION CRACK	الضوء الخلفي
07 Suspension System		ممتص الصدمات
07.A Arms	ARM BUSHES DRY CRACK	ازرع
08 Interior Condition		الحاله الداخليه
08.A AC Condition	OK,REAR GRILL PORTION LOOSE	المكيف

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae