



## TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	25 Apr 2022, 10:42:57
Transaction Number	96136651 (CC10008)	Queue Number	312309



Chassis Number	KNADN4129F6440117
Engine Number	
Vehicle Class	Car
Manufacturer	Kia
Model	Rio
Model Year	2015
Color	White
Mileage	253028 Km
Fuel Type	Petrol
No. Of Cylinders	4
Specification	GCC Specification

DEFECT	REMARKS	
<b>01 Body</b>		<b>جسم المركبة</b>
01.A Trunk	REPAINTED,PORZION REPAIRED	صندوق
01.B Paint	BODY PORTION REPAINTED,PORZION REPAIRED,MINOR DENT,SCRATCHES	الصبغ
01.C Doors	LEFT SIDE BOTH DOOR REPAINTED,PORZION REPAIRED&REAR RIGHT SIDE REPAINTED	أبواب
01.D Fenders	REAR BOTH SIDE REPAINTED,REPAIRED&FRONT BOTH SIDE REPAINTED	مدكار
01.E Floor	BACK PANEL , QUATER PANEL REPAIRED	الارضية
01.F Sign of back accident		وجود مؤشر لحادث في الخلف
01.G Sign of side accident		وجود مؤشر لحادث في الجانب
01.H Pillars	C/PILLAR OUTER REPAIRED	القوائم
<b>02 Engine Condition</b>		<b>المحرك</b>
02.A Visual Engine Condition	SIGN OF MINOR OIL LEAK	حالة المحرك النظري
<b>03 Transmission Condition</b>		<b>الجير</b>
03.A Visual Gear Box Condition	MINOR OIL LEAK	حالة الجير النظري
03.B Road Test	NOT CHECK	فحص علي الطريق

DEFECT	REMARKS	
<b>04 Steering Condition</b>		المقود
04.A Axel	FRONT LEFT SIDE INNER AXLE BOOT CUT	اكسلات
<b>05 Suspension System</b>		ممتص الصدمات
05.A Arms	FRONT LOWER ARM BUSH CRACKED	ازرع
<b>06 Chassis Condition</b>		الشاصي
06.A Chassis	REAR CHASSIS EXTENSION END REPAIRED	الشاسيه
<b>07 Interior Condition</b>		الحاله الداخليه
07.A AC Condition	OK	المكيف
07.B Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
<b>08 Battery Condition</b>		حالة البطارية
08.A Battery bracket	MISSING	حامل البطارية
<b>09 Tires and Rims Condition</b>		الاطارات
09.A Rear Tyre	BOTH SIDE 2019	الاطار الخلفي
09.B Front Tyre	LEFT SIDE 2019 CRACKED & RIGHT SIDE 2021	الاطار الامامي
<b>10 Seats Condition</b>		المقاعد
10.A Seat Condition	DRIVER SEAT HAVE MINOR CUT	حالة المقاعد

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

# Test Certificate



Vehicle  
Registration



X FAILED

Transfer Certificate :	62193789
Chassis No :	KNADN4129F6440117
Vehicle Make :	KIA
Vehicle Model :	RIO
Vehicle Class :	Light Vehicle
Body Type :	SALOON
Fuel :	Benzene
Color :	White
Drive Direction :	--
Dimensions : (H x W x L) :	-- x -- x --
Current Odometer :	253028 Kms.
Origin :	South Korea
Model Year :	2015
Gear Type :	Automatic
Engine Size :	2000 CC
Engine No :	G4FAES75...
Horse Power :	75
Axles No :	2
Cylinders :	4
No Of Doors :	4
No Of Seats :	5
G. V. W. :	Empty Weight : 1200 Kgs. 1650 Kgs.

Certificate Number :	5-TAS-2022-16725074
Inspection Date :	09-05-2022
Certificate Print Date :	09-05-2022
Services :	Registration Test
Vehicle Testing Partner :	Tasjeel
Vehicle Testing Center :	Tasjeel Al Aweer
Total Time Taken :	14 min 28 sec
Appointment Ref Number :	--
Start Time :	15:29
End Time :	15:44
Lane :	01
Token No. :	255
Attempt :	1
Prints No :	1

## Parameter Readings

Service brake imbalance on front axle 6 %	Service brake imbalance on rear axle 10 %	Parking brake imbalance between LHS and RHS 5 %	Vehicle on Petrol CO Reading 0 %
Vehicle on Petrol HC Reading 4 PPM VOL			

## Inspection Findings

Defects	Issue	Severity
Tire change rear right side tire inner worn out	Worn out tread tire	Major
Stop lamps fix both side brake lights	Bulb busted	Major

Inspection Remarks: left side running board, rear compartment panel repaired/rear left side extension end dent

## Payment Details

Inspection Performed by 8008085 34439	Payment Method VTP Credit Account	Transaction Number 16725074	Service Fees AED 170 Collected on 09/05/2022
Parking Slot No --	Service Name Registration Test	Attempt 1	Received by Bajurdeen Abdul Gafoor

- This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.
- Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

تستخدم هذه الشهادة حصرا في العمليات الخاصة بالتريخيص الفني للمركبة. لا يعتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلاف عملية تريخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص



This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.