CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2937009
Transaction Date	06 Nov 2026, 10:14:54
Site Name	840 - Emirates Auctions
Transaction Number	46789973 (CC10008) (CC10011)



Vehicle Details

Chassis Number	MDHBN7AD6D*******
Specification	GCC Specification
Make	Nissan
Model	Sunny
Model Year	2013
Color	White
Mileage	300697 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	REAR BOTH SIDE REPAINTED PORTION REPAIRED & FRONT BOTH REFITTED MISALIGN	مدكار
01.B Paint	BODY PORTION REPAINTED,PORTION REPAIRED,DENTS SCRATCHES,PORTION FADED RUSTY	الصبغ
01.C Doors	FRONT RIGHT SIDE REPLACED,REAR RIGHT REPAINTED PORTION REPAIRED	أبواب
01.D Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.E Bumper	MISALIGN PORTION DAMAGED,TOWING HOOK COVER MISSING	دعامية
01.F Windshield	FRONT DAMAGED	زجاج
01.G Bonnet	RELEASE HANDLE DAMAGED,DEEP DENTS	غطاء المحرك
01.H Pillars	RIGHT SIDE B/PILLAR REPAIRED	القوائم
01.I Trunk	REPAIRED REPAINTED,REFITTED	صندوق
01.J Sign of front accident	BULK HEAD ,RADIATOR SUPPORT REPAIRED	وجود مؤشر لحادث في المقدمة
01.K Sign of side accident		وجود مؤشر لحادث في الجانب
01.L Sign of back accident		وجود مؤشر لحادث في الخلف
02 Chassis Condition		الشاصي
02.A Chassis	FRONT RIGHT SIDE CHASSIS END REPAIRED ,LEFT SIDE END DENT	الشاسيه
03 Engine Condition		المحرك
03.A Smoke	WHITE	دخان

Condition	Remarks	الحالة
03.B Engine Visual Condition	PARTS GETTING RUSTY ,OIL WET ,REFITTED ,ABNORMAL NOISY	الحالة النظريه للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	SEAT,SIDE COVER PORTION DAMAGED,EXTRA COVER	حالة المقاعد
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	REFITTED ,PARTS GETTING RUSTY	الحالة النظريه للجير
05.B Road Test	NOT CHECK	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2021 CRACKED EXPIRED	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2021 CRACKED EXPIRED	الاطار الخلفي
06.C Rims Condition	PORTION DENTS GETTING RUSTY	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	RIGHT SIDE LENS GETTING FADED	الاضاءة الرئيسية
07.B Tail Light	LEFT SIDE CRACK	الضوء الخلفي
07.C Brake Light	LEFT SIDE NOT WORKING	نور الفرامل
08 Suspension System		ممتص الصدمات
08.A Arms	BUSHES CRACK	ازرع
09 Steering Condition		المقود
09.A Axle	FRONT BOTH SIDE OUTER BOOT CUT	اكسلات
10 Interior Condition		الحاله الداخليه
10.A Other	INTERIOR PARTS GETTING RUSTY,SIGN OF FLOODED	اخري
10.B Mirror	RIGHT SIDE ADJUSTMENT LEVER DAMAGED	المرايا
10.C AC Condition	NO COOLING,BLOWER NOISY	المكيف
10.D Power Window Switch And Glass	FRONT RIGHT SIDE HANDLE WORN OUT	مفتاح النافذه و الزجاج
10.E Audio	ANTENNA DAMAGED	صوتيات
10.F Roof Ceiling	DIRTY	بطانه السقف
10.G Sun Visor	MISALIGN	حاجب الشمس
10.H Odometer reading	CLUSTER COVER PORTION CRACKED	قراءة عداد المسافات
10.I Door Panel	PORTION DAMAGED	لوحة بطانة الباب
10.J Steering Wheel and control buttons	WORN OUT,PORTION MELTED	عجلة القيادة وازرار التحكم
10.K Gear Shifting Lever	KNOB WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر **wecare@carscheck.ae**